


STREET CENTERLINE TIES



LEGEND

| |
|--|
| ○ = FD WELL MON W/HEX BAR TYP. |
| △ = L/T CITY OF GARDEN GROVE SURVEYOR |
| ○ = SET L/T LS 4240 TYP. / TANGENT OVER. |
| ● = SPK/W CITY OF GARDEN GROVE SURVEYOR |
| ∅ = TANGENT OVER. |

GRAPHIC SCALE

30 0 15 30



FEET

CAL VADA


SURVEYING, INC.

Los Angeles • San Francisco • Denver • Phoenix
108 Business Center Drive, Corona, CA 92880-1782 Phone: (909) 280-9960 Fax: (909) 280-9746 (800) CALVADA (225-8232)

Job No 02232

www.calvada.com

STREET CENTERLINE TIES



LEGEND

| | |
|-----|-------------------------------------|
| ○ = | SET L/T LS 4240 TYP. / TANGENT OVER |
| ◇ = | FD WELL MON W/HEX BAR TYP. |
| △ = | L/T CITY OF GARDEN GROVE SURVEYOR |
| ∅ = | TANGENT OVER. |

GRAPHIC SCALE

30 0 15 30



FEET

CAL VADA


SURVEYING, INC.

Los Angeles • San Francisco • Denver • Phoenix
108 Business Center Drive, Corona, CA 92880-1782 Phone: (909) 280-9960 Fax: (909) 280-9746 (800) CALVADA (225-8232)

www.calvada.com

Job No 02232

STREET CENTERLINE TIES



LEGEND

| | |
|--|-----------------------------------|
| | FD WELL MON W/HEX BAR TYP. |
| | L/T CITY OF GARDEN GROVE SURVEYOR |
| | TANGENT OVER. |

GRAPHIC SCALE

30 0 15 30



FEET

CAL VADA


SURVEYING, INC.

108 Business Center Drive, Corona, CA 92880-1782 Phone: (909) 280-9960 Fax: (909) 280-9746 (800) CALVADA (225-8232)

www.calvada.com

Job No 02232


STREET INTERSECTION TIES



LEGEND

- | | |
|-------------|---------------------------------------|
| \circ | = SET L/T LS 4240 TYP. / TANGENT OVER |
| \circ | = FD WELL MON W/HEX BAR TYP. |
| \triangle | = L/T GARDEN GROVE SURVEYOR TAG |
| Φ | = TANGENT OVER. |

GRAPHIC SCALE



FEET

CALVADA


SURVEYING, INC.

108 Business Center Drive, Corona, CA 92880-1782 Phone: (909) 280-9960 Fax: (909) 280-9746 (800) CALVADA (225-8232)

Job No 02232

www.calvada.com

STREET INTERSECTION TIES



LEGEND

| | |
|-----|-------------------------------------|
| ○ = | SET L/T LS 4240 TYP. / TANGENT OVER |
| ◇ = | FD WELL MON W/HEX BAR TYP. |
| △ = | L/T CITY OF ANAHEIM SURVEYOR |
| Φ = | TANGENT OVER. |

GRAPHIC SCALE

30 0 15 30



FEET

CALVADA


SURVEYING, INC.

Los Angeles • San Francisco • Denver • Phoenix
108 Business Center Drive, Corona, CA 92880-1782 Phone: (909) 280-9960 Fax: (909) 280-9746 (800) CALVADA (225-8232)

Job No 02232

www.calvada.com

STREET CENTERLINE TIES



LEGEND

- | | |
|------------------------|-------------------------------------|
| <input type="circle"/> | SET L/T LS 4240 TYP. / TANGENT OVER |
| <input type="circle"/> | FD WELL MON W/HEX BAR TYP. |
| <input type="circle"/> | TANGENT OVER. |

GRAPHIC SCALE

30 0 15 30



FEET

CAL VADA


SURVEYING, INC.

Los Angeles • San Francisco • Denver • Phoenix
108 Business Center Drive, Corona, CA 92880-1782 Phone: (909) 280-9960 Fax: (909) 280-9746 (800) CALVADA (225-8232)

Job No 02232

www.calvada.com

STREET CENTERLINE TIES



LEGEND

| | |
|-----|-------------------------------------|
| ○ = | SET L/T LS 4240 TYP. / TANGENT OVER |
| ◇ = | S & W CTY ENG. |
| △ = | FD NAIL |
| ∅ = | TANGENT OVER. |

GRAPHIC SCALE

30 0 15 30



FEET

CALVADA


SURVEYING, INC.

108 Business Center Drive, Corona, CA 92880-1782 Phone: (909) 280-9960 Fax: (909) 280-9746 (800) CALVADA (225-8232)

Job No 02232

www.calvada.com

STREET CENTERLINE TIES




LEGEND

- = SET L/T LS 4240 TYP. / TANGENT OVER
- ◇ = FD WELL MON W/BRASS DISK LS 5458
- △ = FD 1 1/2 BR DISK
- ⊟ = TANGENT OVER.

GRAPHIC SCALE

30 0 15 30



FEET

CALVADA

SURVEYING, INC.


Los Angeles • San Francisco • Denver • Phoenix
108 Business Center Drive, Corona, CA 92880-1782 Phone: (909) 280-9960 Fax: (909) 280-9746 (800) CALVADA (225-8232)

Job No 02232

www.calvada.com

City of CARLTON CENTER County of SACRAMENTO, California

Brief Legal Description INT. MONROE ST. & LAMPSON AVE



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 8/2/04

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

LAMPSON AVE IS TO BE REPAVED. THIS CR IS FOR THE PURPOSE OF PERPETUATING THE SURVEY EVIDENCE IN THIS LOCATE.


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Aug 13, 2004

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT
AUG 23 2004

This Corner Record was received _____

and examined and filed OCT 13 2004


Signed MICHAEL K. SULLIVAN L.S. No. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

FO CHS + IN TC. NO REF.
SET CTT LS 4743




SET
CTT LS 4743
IN TC.

TRACT NO 3323
MM 102/20-24

1/10 SCALE

CORNER RECORD

City of Garden GroveDocument Number 2005-0924BCounty of ORANGE, CaliforniaBrief Legal Description 2117 MAROON ST. & CYPRESS AVE**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 11/18/04**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:


SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action July 5, 2005

Signed Bethell L.S. or R.C.E. No. 0743

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JUL 13 2005


and examined and filed AUG 18 2005

Signed J.C. Kehler L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____




○ = SET S&W LS 4743

● = FD LTT LS 4743 PER CR 2004-136BA MTC.

ALL DISTANCES ARE MAGR PER CR 2004-136BA

City of YUKON CREEKCounty of GRANDE

, California

Brief Legal Description SW COR OF RS 241

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 8/2/04

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

LAMSON AVE IS TO BE REPAVED. THIS CR IS FOR THE PURPOSE
OF PERPETUATING THE SURVEY MONUMENTS IN THIS LOCATE.


A description of the physical condition of the monument as found and as set or reset:

See PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Ac 06 13, 2004

Signed Brace G. Hall L.S. or R.C.E. No. 0743

COUNTY SURVEYOR'S STATEMENT
AUG 23 2004

This Corner Record was received _____

and examined and filed OCT 13 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. LS. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

RS 2411

SET LTT LS 4743
IN TC 28.2' WEST
OF WEST TOP OF
X OF DRIVEWAY.

FD CHAS + IN TC NO REF
SET LTT LS 4743

ELAMSON
AVE.

TO SECTION 1321.67'
LINE @
BEACH BLVD

ED 1" IRON PIPE WITH NAR
& CONCRETE DN 2° PER
RS 2411

1321.66 TO & DALE

10 SEC 6

SET LTT LS 4743
IN TC @ TOP OF
X TO DRIVEWAY

SET LTT LS 4743
IN TC 10' EAST
OF TOP OF X
TO DRIVEWAY

RS 14/30


CORNER RECORD

City of Glenview Grove

Brief Legal Description E LAMPSON AVE. 1321.66' W/ E DALE

Document Number 2005-0932B

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input checked="" type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 11/18/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See Pg 2

A description of the physical condition of the monument as found and as set or reset:

See Pg 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on JULY 5, 2005

Signed B.G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

JUL 13 2005

This Corner Record was received _____

and examined and filed AUG 18 2005


Signed J.C. Kuhn L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

RS 24/1



RS 14/30

○ = SET SFW LS 4743

● = FD LTT LS 4743 IN TC PER CR 2004-1367A


ALL DISTANCES ARE MGR PER CR 2004-1367A.

NO SCALE

City of CHOCOON CREEKCounty of ORANGE

, California

Brief Legal Description

POINT OF ARROWHEAD ST. & LAMPSON AVE.

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 8/2/04

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial U.S. Survey foot Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

LAMPSON AVE IS TO BE REPAVED THIS CR IS FOR THE
PURPOSE OF PERPETUATING THE SURVEY MONUMENTS IN THIS
LOCATE.

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on AUG 23, 2004

Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 23 2004and examined and filed OCT 13 2004Signed Michael K. Sullivan L.S. or R.C.E. No. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment

RS 24/1

SET CTT LS4743
INTC

56.15'

329.81

(329.80' PER
MM273/50-51
PMB 30/45
PMB 94/21-22)NO SCALE
DO NOT USE UNLESS
SOMETHING IS WRONGIS CS/FCZ WAY
22-13 TOWARD SOUTHEAST
NO DEF. ACC. IN ST.
IS CS/FCZ WAY
22-13 TOWARD SOUTHEAST
NO DEF. ACC. IN ST.

82.52'

55.91'


(991.51' PER PMB 30/45
MM273/50-51
TO E
991.85 DATE →
ST.

61.26'

DE LAMPSON AVE

SET CTT LS 0703
INTCFD LEAD &
PACK INTC
NO REP
SET TAG LS4743TRACT 3323
MM 102/20-22

CORNER RECORD

Document Number 2005-0925BCity of GARDEN GROVESCounty of Orange, Calif.Brief Legal Description SW 1/4 OF ARROWHEAD ST. OF LAMPSON AVE**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 11/18/04**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt



Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See PG 2

A description of the physical condition of the monument as found and as set or reset:


See PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on July 6, 2005

Signed Bruce G. Hall L.S. or R.C.E. No. 4703**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received JUL 13 2005and examined and filed AUG 18 2005Signed J.C. Hahn L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____


2/10 scale



O = SET SAW LS 0743

● = FD LTT LS 0743 IN TC PER CR 2004-1366A

ALL DISTANCES ARE MTR PER CR 2004-1366A




CORNER RECORD

City of GARDEN GROVE

Brief Legal Description SW 1/4 of NW 1/4 of SW 1/4 of Campson Ave.

Document Number 2005-0926B

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input checked="" type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 4/9/05

COORDINATES (Optional)

| | | |
|---|---------------------------------|-----------------------------------|
| N. | <hr/> | |
| E. | <hr/> | |
| Zone | NAD27 <input type="checkbox"/> | NAD83 <input type="checkbox"/> |
| NAD83 Epoch _____ | | |
| Elev. | <hr/> | |
| Vert. Datum: | NGVD29 <input type="checkbox"/> | NAVD88 <input type="checkbox"/> |
| Meas. Units: | Metric <input type="checkbox"/> | Imperial <input type="checkbox"/> |
| U.S. Survey foot <input type="checkbox"/> | | |

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

See Page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action July 5, 2005

Signed B.G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 13 2005

and examined and filed AUG 18 2005

Signed J.C. Hornecker L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

FD LTT CS
6629 N TC
PER CR
2004-1365A

FD LTT LS 4763
IN TC PER
CR 2004-1365A

FD LTT LS 4763
IN TC PER
CR 2004-1365A

FD OC SURVEYOR
BM STAMPED
RCE 7872 N TC
PER CR 2004-1365A

LEGEND.

- O = SET SAW 4763
- = FD MARKMENT AS NOTED

ALL DISTANCES ARE IN FEET
PER CR 2004-1365A

OCS 4763 3627 SEC INT.
80' 0" FEET ON SWH COVE
SET 4763 SET 4763 PERIOD.

74.83'

ELAMPOON AVE.

IDENTICAL POINTS

8/11 2' 0" E 000 57
8/11 3' 0" N 000 57
3' 00"

ELAMPOON
AVE.


DETAIL

/ NO SCALE

City of CITY OF CLOVISCounty of VISALIA

, California

Brief Legal Description

AT INT. OF LAMPSON AVE & DALE STREET

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey AUG 2, 2004

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

PK'S & TAGS @ E OF LAMPSON & DALE WILL BE DESTROYED
BY PAVING EFFORTS.

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on AUG 13, 2004

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received AUG 23 2004

and examined and filed OCT 13 2004


Signed Michael K. Sullivan L.S. or R.C.E. No. 6254
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



City of GARDEN GROVE County of ORANGE, California
Brief Legal Description INT EUCALO ST & ORANGEWOOD AVE



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 7/2004

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. MAJOR STREET REHAB IS TO TAKE PLACE WITHIN EUCALO STREET. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY EVIDENCE & MONUMENTS IN THIS LOCALE

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on AUG 10, 2004

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 23 2004

and examined and filed OCT 13 2004


Signed Michael K. Sullivan L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment

City of GARDEN GROVE County of ORANGE, California
Brief Legal Description # M.T. EUCLID ST & DUDLEY AVE.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey 7/23/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PAGE 2. MAJOR PAVEMENT & CONCRETE REMOVAL & REPAIR IS TO TAKE PLACE ON EUCLID ST.
THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS & EVIDENCE IN THIS LOCALE


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Aug 14, 2004

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 23 2004


and examined and filed OCT 13 2004

Signed Michael K. Sullivan L.S. No. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment




O = SET LTT LS 4743 IN TC UNLESS OTHERWISE NOTED

• = FD L&T IN TC PER CITY OF ANAHEIM TB 53/278 UNLESS OTHERWISE NOTED

() = RECORDED PER CITY OF ANAHEIM TB BOOK 53/278

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0918BCounty of ORANGE, California
Brief Legal Description S INT ECUO ST. & DUDLEY AVE.

CORNER TYPE

Government Corner

 Control

Meander

 Property

Rancho

 Other Date of Survey 4/18/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:


SEE PG 2

A description of the physical condition of the monument as found and as set or reset:


SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Decay 4, 2005Signed Bruce G. HallL.S. or R.C.E. No. 2743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 07 2005and examined and filed AUG 15 2005Signed John C. HorneckerL.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

1 no scale2

49.21'

80.0'

REDWOOD ST.

35.96'

58.18'

36.26'

65.50'

EDDIE X AVE.

○ = GCT SCAR HEAD SDW LS 6743

● = FD LTT LS 6743 IN TC PER CR 2004-1349A

▲ = FD LTT LS 6743 IN WALK PER CR 2004-1349A


ALL DISTANCES ARE WALK PER CR 2004/1349A

City of ANAHEIM

County of ORANGE

, California

Brief Legal Description EAST SIDE OF EUCLID ST. 685¹/₂ N/ ORANGEWOOD AVE.



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 7/28/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. MAJOR STREET REHABILITATION IS TO TAKE PLACE IN EUCLID ST. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS & EVIDENCE IN THIS LOCALE.

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Aug 26, 2004

Signed Bruce G. Hall L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 28 2004
and examined and filed OCT 13 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment



○ = SET LTT LS 4743 IN T.C. UNLESS OTHERWISE NOTED.

● = FD 1½" dia. disc in conc. wall stamped "ORANGE COUNTY SURVEYOR AB 19 8185" NO REF.

CORNER RECORD


City of ANAHEIM

Document Number 2005-0919B

County of ORANGE

, California

Brief Legal Description EAST SIDE OF EUCALYPTUS ST. 685' T N/ ORANGEWOOD AVE.



CORNER TYPE

Government Corner

Control

Meander

Property

Rancho

Other

Date of Survey 8/8/05

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action JULY 4, 2005

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 15 2005 JUL 07 2005

and examined and filed

Signed JON C. HORNECKER L.S. or R.C.E. No. 7212

Title ORANGE COUNTY SURVEYOR




County Surveyor's Comment

E. ADDISON - BAKER CITY CHANNEL

NO SIGHT

at 0100 51'




O = SET LTT LS 0703 IN WALK

● = FD LTT LS 0703 IN TC PER CR 2004-1348A UNLESS
OTHERWISE NOTED

ALL DISTANCES ARE MEASURED PER CR 2004-1348A.

O = SET LT7 LS0743 IN TC.

~~NO SETS~~




City of GARDEN GROVE

County of ORANGE

, California

Brief Legal Description

6 ECUCLID ST. 175' N/1 ORANGEWOOD AVE.



CORNER TYPE

Government Corner

Control

Meander

Property

Rancho

Other

Date of Survey 7/29/04

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. MAJOR STREET REHABILITATION IS TO TAKE PLACE IN ECUCLID STREET. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS & EVIDENCE IN THIS LOCALE

A description of the physical condition of the monument as found and as set or reset:


SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on AUG 11, 2004

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

AUG 23 2004

This Corner Record was received _____

and examined and filed OCT 13 2004 L.S. No. 6254


Signed Michael K. Sullivan L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

SET CTT CS 6703
S 1st NUCK



ERIECCA AVE

NOTE: I WAS UNABLE TO FIND A REFERENCE AT THE CITY OF GLENDALE CEMETERY OR AT THE CITY OF PHOENIX POLICE DEPARTMENT FOR THE 2004-1355 A SET. I WAS UNABLE TO FIND A REFERENCE AT THE CITY OF GLENDALE CEMETERY OR AT THE CITY OF PHOENIX POLICE DEPARTMENT FOR THE 2004-1355 A SET.


No Survey

City of GARDEN GROVE

County of ORANGE

, California

Brief Legal Description EUCLID STREET 950TH SOUTH OF KATELLA AVE.



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 7/28/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. MAJOR STREET REHABILITATION IS TO TAKE PLACE
IN EUCLID ST. THE PURPOSE OF THIS CR IS TO PERPETUATE
THE SURVEY MONUMENTS & EVIDENCE IN THIS LOCATE

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on August 16, 2004

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 28 2004


and examined and filed OCT 13 2004

Signed MICHAEL K. SULLIVAN L.S. or R.C.E. No. 6254
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

City of GARDEN GROVE County of ORANGE, California
Brief Legal Description INT EUCUD ST. & CINDY LANE



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 7/28/04

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. MAJOR STREET REHAB IS TO TAKE PLACE WITHIN EUCUD STREET. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY EVIDENCE OF MONUMENTS IN THIS LOCATE

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Aug 14, 2004

Signed Bruce G. Hall L.S. or R.C.E. No. 0743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received AUG 23 2004

and examined and filed OCT 13 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment



- = FOUND LEAD & MARK PER CITY OF GARDEN GROVE THE BOOK & PAGE 91 UNLESS OTHERWISE NOTED IN T.C.
- () = RECORD PER CITY OF GG THE BOOK & PAGE 91


CORNER RECORD

Document Number 2005-0915B

City of Garden Grove

County of Orange, California

Brief Legal Description E INT EUCED & CINDY LANE



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 4/18/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on January 4, 2005

Signed Bruce G. Hall L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT


This Corner Record was received JUL 07 2005

and examined and filed AUG 15 2005

Signed J.C. Hornecker L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____




O = SET BEND HEAD SGM CS 4743

• = FD DEAD STOCK DER CR 2004-1354A

DISTANCES SHOWN ARE MILES PER CR 2004-P54A

City of GARDEN GROVE County of ORANGE, California
Brief Legal Description 2117 EUCALYPT ST & PALMA VISTA AVE



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 7/28/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2. MAJOR STREET REHAB IS TO TAKE PLACE WITHIN EUCALYPT STREET. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY EVIDENCE & MONUMENTS IN THIS LOCALITY.

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Ac 12, 2004

Signed B.G.Hall L.S. or R.C.E. No. 4783



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received AUG 23 2004

and examined and filed OCT 18 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. ES. 6254
Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____



O = SET CTT LS470B INT.C

ALL FOUND MONUMENTS ARE PER CITY OF GG THE BOOK & PAGE 92.
() = RECORD PER CITY OF GG THE BOOK & PG 92.

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0916BCounty of ORANGE, CaliforniaBrief Legal Description NE INT. EUCALYPT ST. & PACHA VISTA AVE

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 4/18/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action Dec 7 4, 2005

Signed Bruce G. Hall L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 07 2005


and examined and filed AUG 15 2005

Signed John C. Hornecker L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



ALL DISTANCES ARE MTR PER CR 2006-1353A


City of GARDEN GROVE

County of ORANGE

, California

Brief Legal Description

4 INT EUCALYPTUS ST. & OAK WAY



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 7/26/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. MAJOR STREET REHAB IS TO TAKE PLACE IN EUCALYPTUS STREET. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS & EVIDENCE IN THIS LOCALE.


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Aug 14, 2004

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

AUG 28 2004

This Corner Record was received _____


and examined and filed OCT 13 2004

Signed MICHAEL K. SULLIVAN L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____



• = FD LEAD & JACK PER CITY OF GARDEN GROVE THE BOOK & PAGE 95 UNLESS OTHERWISE NOTED.

() = RECORD PER CITY OF G.G. THE BOOK & PAGE 95

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0917BCounty of ORANGE, CaliforniaBrief Legal Description NE INT EUCALYPT ST. & ORO WAY

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 4/18/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on July 4, 2005

Signed Bruce G. Hall

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received

JUL 07 2005

and examined and filed

AUG 15 2005


Signed Jon C. Horneck

L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment



○ = GEAR HEAD SAW LS 0703

● = F.D. LEADERSHIP INTC PER CR 2004-1352A

DISTANCES SHOWN ARE MGR PER CR 2004-1352A

FD CENS + IN THE PER CITY OF
GARDEN GROVE THE BOOK & PAGE 107
SET LTTS LS 4743

NO SOURCE

70.02'
(70.02')

43.58'
(43.58')

6 INT. PT. MORTIMER POINT
FALLS ON 5TH COVE

77.92'

E WAKEFIELD
AVE.

70.95'


C EAGLE
STREET

O = SET LTTS LS 4743 IN TC

() = RECORD PER CITY OF GARDEN GROVE
THE BOOK & PAGE 107

City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description # 117 EUCLID ST. & WAKEFIELD AVE

CORNER TYPE

Government Corner

 Control

Meander

 Property

Rancho

 Other Date of Survey 7/28/04

COORDINATES (Optional)

N.

E.

Zone NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial U.S. Survey foot Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PAGE 2. MAJOR STREET REHAB IS TO TAKE PLACE WITHIN EUCLID STREET. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS & EVIDENCE IN THIS LOCATION

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2.

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on AUG 12, 2004Signed B.G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG 23 2004and examined and filed OCT 13 2004Signed Michael K. Sullivan L.S. or R.C.E. No. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

City of GARDEN GROVE County of ORANGE, California
Brief Legal Description 2107 MAGNOLIA PLAMSON



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/01/03

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on JANUARY 27, 2004.

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 09 2004
and examined and filed MAR 01 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254


Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

FO LEAD JACK & TAG
GG SURVEY IN TLC
PER GG7B 1 PG 68A
S IN TL: NO 225

~~NO SCALE~~



FLD 73'

139.02'

CELAMSON
AVE

138.50'

205.69'
E MAGNOLIA

95.82'

167.17'

162.30'

FO LEAD JACK & TAG
"GG SURVEY" IN TLC
PER GG7B 1 PG 68A

FO DURAL BAR IN WERC
MON PER GG7B 1 PG 68A

151.65'

112.70'

LEGEND

- = FO MONUMENT AS NOTED
- ▷ = SET LEAD, JACK & TAG LS 4743 IN TLC
- GG7B = GARDEN GROVE CITY THE BOOK.


CORNER RECORD

Document Number 2005-0923B

City of GARDEN GROVE

County of ORANGE, California

Brief Legal Description 6117 MAGNOLIA AVE.



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 4/19/05

COORDINATES (Optional)

| | | | |
|---|---------------------------------|-----------------------------------|--------------------------------|
| N. | <u> </u> | | |
| E. | <u> </u> | | |
| Zone | <u> </u> | NAD27 <input type="checkbox"/> | NAD83 <input type="checkbox"/> |
| NAD83 Epoch | | <u> </u> | |
| Elev. | <u> </u> | | |
| Vert. Datum: | NGVD29 <input type="checkbox"/> | NAVD88 <input type="checkbox"/> | |
| Meas. Units: | Metric <input type="checkbox"/> | Imperial <input type="checkbox"/> | |
| U.S. Survey foot <input type="checkbox"/> | | | |

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JULY 5, 2005

Signed Bruce G. Hall L.S. or R.S.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 13 2005


and examined and filed AUG 18 2005

Signed J.C. Hall L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



SECTION

FO PK NAL
(CITY OF GG TIE BOOK
7 PAGE CALLS FOR
PK WITH BOSS TAG)

FO LEAD & TIE IN
70 PER CITY OF GG
TIE BOOK 7 PAGE 3

No. 06
(GARDEN)

E CLAWSON AVE

FO STUB OF SPKE
IN AC BER M1 PER
CITY OF GG TIE
BOOK 7 PAGE 3

FO SPR, W & MN PER
CITY OF GG TIE
BOOK 7 PAGE 3 IN
AC BER M1

36.85°
(36.85°)

45.93°
(45.93°)

E CLAWSON ST.


() = RECORD PER CITY OF GARDEN
GROVE TIE BOOK 7 PAGE 3.

● = FOUND MONUMENT AS NOTED

City of CAMPION CORNER

County of LAMARO, California

Brief Legal Description INT CAMPION OF CORNER



CORNER TYPE

- Government Corner Control
Meander Property
Rancher Other

Date of Survey 8/10/03

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Dec 18, 2003

Signed Brace G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

FEB 09 2004

This Corner Record was received _____

and examined and filed MAR 01 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

City of CARMEL BY THE SEA County of CARMEL, California

Brief Legal Description SW 1/4 Josephine St & Lamson Ave

COORDINATES (Optional)



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey 8/10/03

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Dec 16, 2003

Signed Michael K. Sullivan L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 09 2004

and examined and filed MAR 01 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

FO LEAD TACK & TAG LS 2681 NO REF.
(L&T PER TAAGT 10/24)

FO RAMSET NAIL IN TC
PER CITY OF GG THE
BOOK 7 PAGE 2.

EXIST CURB



() = RECORDED PER CITY OF GARDEN
GAVE THE BOOK 7 PAGE 2.


● = FOUND MONUMENT AS NOTED

NO SCENE

CORNER RECORD

Document Number 2005-092013City of Garden GroveCounty of Orange

, California

Brief Legal Description # 117 JOSEPHINE ST. & CAMPBELL AVE**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/30/05**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See Pg 2

A description of the physical condition of the monument as found and as set or reset:

GEO Pg 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on July 5 2005Signed B. Hall L.S. or R.C.E. No. 2743**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received JUL 13 2005
AUG 13 2005

and examined and filed.


Signed J.C. Hornegger L.S. or R.C.E. No. 7212

Title _____



County Surveyor's Comment _____

do scale



○ = SET SAW LS 4743

▲ = FD RAMSET NAIL IN TC PER CR 2004-0229

● = FD LTT LS 2681 PER CR 2004-0229


ALL DISTANCES ARE MGR PER CR 2004-0229

City of GARDEN CITY

County of SAN JOSE

, California

Brief Legal Description INT CAMPSON AVE & AESTOCRAT AVE



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey Sept 3

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Dec 30, 2003

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 09 2004


and examined and filed MAR 01 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



O = SET CEMO MARK & TAG LS 6723 IN T.C.

() = RECORDED PER CITY OF GARDEN GROVE TIC BOOK 7 PG 48.


● = FOUND MONUMENT AS NOTED

(ALSO, SEE CR 2004-0232 FOR ADDITIONAL DATA)

CORNER RECORD

City of Garden GroveDocument Number 2005-0922BCounty of Orange

, California

Brief Legal Description SW 1/4 PT PENTAGON ST. & WATSON AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/30/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
See Pg 2

A description of the physical condition of the monument as found and as set or reset:
See Pg 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action July 5 2005

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 13 2005


and examined and filed AUG 18 2005

Signed J.C. Hornecker L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



○ = SET SAW LS 1703

● = FD LT LS 1703 PER CR 2004-0232

▼ = FD CHS + MTC PER CR 2004-0232

ALL DIST. ARE MGR PER CR 2004-0232


CORNER RECORD

City of GARDEN GROVE

Document Number 2005-0921B

County of ORANGE, California

Brief Legal Description 4 INT. ARISTOCRAT AVE & CLAMPSON AVE



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 12/30/04

COORDINATES (Optional)

| | |
|--------------|---|
| N. | <u></u> |
| E. | <u></u> |
| Zone | <u></u> NAD27 <input type="checkbox"/> NAD83 <input type="checkbox"/> |
| NAD83 Epoch | <u></u> |
| Elev. | <u></u> |
| Vert. Datum: | NGVD29 <input type="checkbox"/> NAVD88 <input type="checkbox"/> |
| Meas. Units: | Metric <input type="checkbox"/> Imperial <input type="checkbox"/> U.S. Survey foot <input type="checkbox"/> |

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:


SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action JULY 5, 2005

Signed B. Hall

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 18 2005

and examined and filed AUG 18 2005


Signed J.C. Hornecker

L.S. or R.C.E. No. 7212


Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment



NO SOURCE




O = SET LEAD, JACK & TAB US 0743 IN T.C.

() = RECORD PER CITY OF GARDEN GROVE THE BOOK 7 PG 48.

● = FOUND MONUMENT AS NOTED.

(ALSO, SEE CR 2004-0231 FOR ADDITIONAL DATA)

City of CARSON CITY County of CHAMBERLAIN, California
Brief Legal Description INT. PENTAGON ST & LAMSON AVE.



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 8/10/03

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Dec 22, 2003

Signed Brace G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT
FEB 09 2004

This Corner Record was received _____

and examined and filed MAR 01 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. LS. 6254


Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

City of GARDEN GROVE County of ORANGE, California

Brief Legal Description of my magnolia at Campson Ave



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/11/03

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See Page 2

A description of the physical condition of the monument as found and as set or reset:

See Page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/27/04

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

FEB 09 2004

This Corner Record was received _____


and examined and filed MAR 01 2004

Signed MICHAEL K. SULLIVAN L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

**LEGEND**

- LTT = LEAD, TARE & TIE
- = FOUND MONUMENT AS NOTED
- GG = CITY OF GARDEN GROVE THE BOOK

Z

CORNER RECORD

City of Garden GroveDocument Number 2005-0928BCounty of ORANGE, CaliforniaBrief Legal Description NW cor. Thompson Ave & Magnolia St.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 4/19/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2


A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on July 5, 2005

Signed B. G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 13 2005


and examined and filed AUG 18 2005

Signed J. C. H. L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



Calumet Ave

16 scale

- = SET LTT LS 4743
- = FD LTT LS 4743 IN TC PER CR 2004-1264
- = FD LTT LS 4025 IN TC PER CR 2004-1264

ALL DISTANCES ARE AS IS PER CR 2004-1264


CORNER RECORD

City of GARDEN GROVES

Brief Legal Description MAGNOLIA ST. 108' ± N / E CAMPSON AVE

Document Number 2005-0987B

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input checked="" type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 4/19/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2


A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on July 5, 2005

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 13 2005


and examined and filed AUG 18 2005

Signed JON C. HORNECKER L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____




Campson Ave.


O = SET C77 CS 4743 A7 1'X1' 0/5 X- P.L. PER CR 2004-1265

• = FO UTT CS 4743 INT PER CR 2004-7265.

▲ = FD LTT '96 SURVEY IN TC PER CR 2004-1265

ALL DISTANCES ARE MSL PER CR 2004-1265






● = FD LTT "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK
7 PG 35 UNLESS OTHERWISE NOTED,

() = RECORD PER CITY OF GARDEN GROVE TIE BOOK 7 PG 35.

CORNER RECORD

City of GARDEN GROVEDocument Number 2004-1643 ACounty of ORANGE, CaliforniaBrief Legal Description # 91 EUCLID ST & CYNTHIA CIRCLE

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 9/30/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Mens. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETuate THE SURVEY MONUMENTS ALONG EUCLID ST. PRIOR TO MAJOR STREET REHABILITATION.


A description of the physical condition of the monument as found and as set or reset: _____

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 10/2/04

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCT 6 8 2004

and examined and filed OCT 20 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. CS 6254
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

CORNER RECORD


4900-001-5

Document Number _____

City of GARDEN GROVE

County of _____

, California

Brief Legal Description E P1 EUCLID ST & CYNTHIA CIRCLE**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Date of Survey 9/30/04Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS ALONG EUCLID ST. PRIOR TO MAJOR STREET REHABILITATION.


A description of the physical condition of the monument as found and as set or reset: _____

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 10/2/04

Signed B. Hall L.S. or R.C.E. No. 4743

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____


and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0912BCounty of ORANGE, California
Brief Legal Description NE 1/4 PI. EUCLID ST. & CYNTHIA CIRCLE**CORNER TYPE****COORDINATES (Optional)**

- Government Corner Control
Meander Property
Rancho Other

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Date of Survey 4/18/05Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on JULY 4, 2005Signed Bruce G. HallL.S. or R.C.E. No. 2712**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received


JUL 07 2005


and examined and filed

AUG 15 2005Signed John C. HorneckerL.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR


County Surveyor's Comment







CORNER RECORD

City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description E INT OF EUCLID ST & WOODBURY RD,Document Number 2004-1642 A

CORNER TYPE

Government Corner Control:
Meander Property:
Rancho Other:

Date of Survey 9/30/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch: _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found. Evidence used to identify or procedure used to establish or reestablish the corner.
SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS ALONG EUCLID STREET PRIOR TO MAJOR STREET REAS.

A description of the physical condition of the monument as found and as set or reset: _____

- ① = FD LTY "CITY OF GARDEN GROVE" IN TC PER CITY OF GG TIE BOOK 7 PG 38.
② = FD SQU "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 7 PG 38.
SEE SH 72.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 10/2/04

Signed Bruce G. HallL.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCT 8 2004

and examined and filed OCT 8 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254
Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

CORNER RECORD

Document Number _____

City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description E INT OF EUCED ST & WOODBURY RD.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 9/30/01

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; evidence used to identify or procedure used to establish or reestablish the corner:


SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY
MOVEMENTS ALONG EUCED STREET PRIOR TO MAJOR STREET
RELAB.

A description of the physical condition of the monument as found and as set or reset:

- ① = FD LTT "CITY OF GARDEN GROVE" IN TC PER CITY OF GG TIE BOOK 7 PG 38.
② = FD SAW "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 7 PG 38.
SEE SHTZ.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 10/2/01Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____


Title _____

County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0911BCounty of ORANGE

, California

Brief Legal Description INT OF EUCLID ST & WOODSBURY RD.

CORNER TYPE

Government Corner Control Meander Property Rancho Other Date of Survey 4/10/05

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83


NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial U.S. Survey foot Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JULY 4, 2005Signed Bruce G. HallL.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received

JUL 07 2005

and examined and filed

AUG 15 2005Signed J. C. HorneckerL.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment



FO SAW "CITY OF GARDEN GROVE PER CITY OF GG 7B 7/36

TB 7/38

(FOR ROAD SET TAKEN IN C.C.)

CEDARSBURG RD.

LINE NUMBER

TRACT NO. 1626
MM 72/1-2

TRACT NO. 2033
MM 72/1-2

FO C.H.S. + 1/2C NO DEF.
TO BE DESTROYED

65.36' R
(65.36')

62.36' R
(62.36')

105.22'

FO C.H.S.

10.00' (90.00')

(130.00') SEE TRACT NO 2033

65.44' R
(65.44')

93.49'

62.50' R
(62.50')

LINE NUMBER

E BLAKE ST.

FO SAW "CITY OF GARDEN GROVE"
PER CITY OF GG TB 7/36

① = FO LTT "CITY OF GARDEN GROVE" PER CITY OF GG TB 7/37.

② = SET LTT LS 4703 IN T.C.

() = RECORD PER CITY OF GARDEN GROVE THE BOOK 7/37 UNLESS
OTHERWISE NOTED.

③ = NE COR SE 1/4, SE 1/4, SEC 5, T.5S, R10W SBBM PER TRACT NO. 2033
MM 72/1-2, FO NOTHING. REEST PER CITY OF GG THE BOOK 7/37.
BY INTERSECTION OF TIES.

FO SAW "CITY OF GARDEN
GROVE PER CITY OF GG 7/36
76 7/38


SECTION. 100
TRACT NO 28/28-32

TRACT NO. 2233
MM 72/1-2

TO CHAS & MRC NO REF.
TO BE DESTROYED

E BLAKE ST.

C WOODBURY RD




- ① = FO LTT "CITY OF GARDEN GROVE" PER CITY OF GG T.B. 7/37.
- ② = SET LTT LS 4703 IN T.C.
- ③ = RECORD PER CITY OF GARDEN GROVE TIE BOOK 7/37 UNLESS OTHERWISE NOTED.
- = NE COR SE 1/4, SE 1/4, SEC 5, T. 55, R10W SBBM PER TRACT NO. 2433 MM 72/1-2, FO NOTHING. REQUEST PER CITY OF GG TIE BOOK 7/37. BY INTERSECTION OF TIES. NOTHING SET-AREA MAY GET DISTURBED.

CORNER RECORD

Document Number 2004-1641 ACity of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description NE COR SEC 4, SEC 4, SEC 5, T. 55, R. 10W SBAM
& EUCLID ST BETWEEN BLAKE ST & WOODGARD RD.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 9/30/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS ALONG EUCLID ST. PRIOR TO MAJOR STREET REHAB.


A description of the physical condition of the monument as found and as set or reset: _____

SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Oct 2, 2004

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

OCT 9 8 2004

This Corner Record was received _____

and examined and filed OCT 9 8 2004 L.S. or R.C.E. No. 6254

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

CORNER RECORD

Document Number:

City of GARDEN GROVE

County of Orange

, California

Brief Legal Description NE COR SE 1/4, SE 1/4, SEC. 5, T. 55, R. 10W SBBM.

• EUCOLID ST BETWEEN BLAKE ST & WOODBURY RD.

11

CORNER TYPE

Government Corner **Control**
Meander **Property**
Rancho **Other**

Date of Survey 9/30/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS ALONG EUCLID ST. PRIOR TO MAJOR STREET REHAB.


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Oct 2 2004

Signed  L.S. or R.R.E. No. 4243



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received

and examined and filed


Signed _____ **L.S. or R.C.E. No.** _____

Title

County Surveyor's Comment




- ① = FD CHISELED + IN TC PER CITY OF GG 7B 7/36 TO BE DESTROYED.
- ② = FD CHISELED + IN TC PER CITY OF GG 7B 7/36. SET L77 LS 4743.
- ③ = SET L77 LS 4743 IN T.C.
- ④ = RECORD PER CITY OF GARDEN GROVE TIE BOOK 7 PG 36.



- ① = FO CHISLED + IN TC PER CITY OF GG TB 7/36 TO BE DESTROYED.
- ② = FO CHISLED + IN TC PER CITY OF GG TB 7/36. SET LTT LS 4743.
- ③ = SET LTT LS 4743 IN T.C.
- () = RECORDED PER CITY OF GARDEN GROVE TIE BOOK 7 PG 36.

CORNER RECORD

Document Number 2004-1640 ACity of Garden GroveCounty of Dorothy, CaliforniaBrief Legal Description #187 EUCID ST & BLAKE ST.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 9/30/04

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE
THE SURVEY MONUMENTS ALONG EUCID STREET PRIOR TO
MAJOR STREET REHAB.

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 10/2/04Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received OCT 6 8 2004and examined and filed OCT 26 2004Signed Michael K. Sullivan L.S. or R.C.E. No. 6254
Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of B朗科, CaliforniaBrief Legal Description E INT EUCLID ST & BLAKE ST.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 9/30/04**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE
THE SURVEY MONUMENTS ALONG EUCLID STREET PRIOR TO
MAJOR STREET REHAB.


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 10/2/04

Signed Bruce G. Hall L.S. or R.C.E. No. 4743

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____


CORNER RECORD

City of GARDEN GROVE

Brief Legal Description L INT EUCO ST. & BLAKE ST.

Document Number 2005-0910B

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 4/18/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on July 4 2005

Signed BRUCE G. HALL

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 07 2005


and examined and filed AUG 15 2005

Signed RON C. HORNECKER L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment



○ = SET GEAR HEAD SET IN LS 0743

● = FD LTT LS 0743 IN TC PER CL 2004-1640A


ALL DISTANCES ARE METER PER CL 2004-1640A



① = FO LTT "GARDEN GROVE SURVEY RP" PER CITY OF
GARDEN GROVE ZIE BOOK 7 PAGE 39.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMMED DATUM & ARE SHOWN FOR CONVENIENCE ONLY.


~~44-6004-1034 A~~



① = FD LTT "GARDEN GROVE SURVEY RD" PER CITY OF
GARDEN GROVE THE BOOK 7 PAGE 39.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE ONLY.

CORNER RECORD

Document Number 2004-1639 ACity of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description INT PUCIO ST AT 32 Fwy ON-OFF RAMP

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey 9/3/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Mens. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE THE
GIVEN MONUMENTS ALONG PUCIO STREET PRIOR TO MAJOR
STREET REHAB


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Oct 2, 2004

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCT 08 2004

and examined and filed OCT 26 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment


CORNER RECORD

City of Garden Grove

Document Number _____

County of Orange, California

Brief Legal Description INT EUCALO ST AT 22 FWY ON-OFF RAMP



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey 9/3/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2. THE PURPOSE OF THIS CR IS TO PERPETUATE THE SURVEY MONUMENTS ALONG EUCALO STREET PRIOR TO MAJOR STREET REHAB

A description of the physical condition of the monument as found and as set or reset: _____

SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Oct 2, 2004

Signed B.G. Hall

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____


County Surveyor's Comment _____

CORNER RECORD

City of Garden Grove

County of ORANGE, California

Brief Legal Description 2 INT ECUADOR ST & AVOCENCIA PLACE



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3/6/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on July 1, 2005

Signed [Signature]

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 07 2005

and examined and filed AUG 15 2005


Signed [Signature] L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____


FD LT "CITY OF SHERIFF'S OFFICE"
MTC DIZ CR 2005-0019



- = SET GEM HEAD SIGN LS 0743
- = FD LT LS 0743 IN TC PER CR 2005-0019
UNLESS OTHERWISE NOTED.

ALL DISTANCES ARE MGR PER CR 2005-0019.

CORNER RECORD

City of GARDEN GROVECounty of ORANGEBrief Legal Description #117 EUCALYPT ST. & AVOCENCIA PLACEDocument Number 2005-0019**CORNER TYPE**

Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/30/04**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**


This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Action 12/30/04Signed Bruce Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**
JAN 04 2005


This Corner Record was received

JAN 19 2005

and examined and filed

Signed Robert Jelinek L.S. or R.C.E. No. 6803Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment



- ▲ = FD SURVEYOR'S RECE 29203 PER TRACT NO. 15932 MM 791/02-45
- = FD LTT "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK II PG 89
- = SET LTT LS 4743

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM AND ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

City of GARDEN GROVEBrief Legal Description BLKTDocument Number 2005-0017County of ORANGE, California

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/30/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/31/05


Signed B. H. Hall L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 04 2005
and examined and filed JAN 19 2005

Signed Robert Jelinek L.S. or R.C.E. No. 6803
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____




CORNER RECORD

City of Garden Grove

Brief Legal Description INT PYRAMIDA PEUERO ST.

Document Number 2005-0913B

County of Orange, California



CORNER TYPE

Government Corner

Control

Meander

Property

Rancho

Other

Date of Survey 3/6/05

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on July 5 2005

Signed B. Hall L.S. or R.C.E. No. 2703



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 07 2005

and examined and filed AUG 15 2005

Signed J. C. Hornbeck L.S. or R.C.E. No. 7212

Title DEPT OF COUNTY SURVEYOR



County Surveyor's Comment _____

FO LTT LS 3047
PER CR 2005-0017

E PACHAYRA DRIVE

LOCUS S7

07.96'


53.96'

76.65'

54.055

○ = SET GEAR NO SPARE & WASHED LS 4X4
● = FO LTT "CITY OF GARDEN GROVE" PER CR 2005-0017
UNLESS OTHERWISE NOTED

ALL DISTANCES ARE MEASURED PER CR 2005-0017.




LEGEND

- INDICATES SET LEAD AND TRACK
L.S. 7707 ON TOP OF CURB.
- △ INDICATES SET SPK AND W TAG
L.S. 7707



| | | | |
|---|------|---|---|
| CITY OF GARDEN GROVE | | STREET TIES | SCALE: 1"=40' |
| DMS CONSULTANTS. 12377 Lewis Street #101 Garden Grove, CA 92840 Phone (714) 740-8841 Fax (714) 740-8842 | | TRACT No. 16433 GILBERT STREET | |
| TIE BOOK | PAGE | WALTER F. LUNDIN L.S. No. 7707 | <i>Walter F. Lundin</i> DATE: 12/27/04 |




LEGEND

- INDICATES SET LEAD AND TRACK
L.S. 7707 ON TOP OF CURB.
- INDICATES SET GEAR SPK W/WASHER
TAGGED L.S. 7707.



| | | |
|---|-----------------------------------|------------------------------------|
| CITY OF GARDEN GROVE | STREET TIES | SCALE: 1"=40' |
| DMS CONSULTANTS. 12377 Lewis Street #101 Garden Grove, CA 92840 Phone (714) 740-8841 Fax (714) 740-8842 | TRACT No. 16433 HALEKULANI DR | |
| TIE BOOK _____ PAGE _____ | WALTER F. LUNDIN L.S. No. 7707 | walter f. lundin DATE: 12/22/04 |




- = FO LTT "CITY OF GARDEN GROVE" PER CITY OF GARDEN GROVE TIE BOOK & PG 57A.
- △ = FO SPK W & TAG "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK & PG 57A.
- = SET LEAD TACK & TAG LS 0743
- () = RECORD PER CITY OF GG TIE BOOK & PG 57A.

THE BEARINGS SHOWN HEREIN ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

City of GARDEN GROVE
County of ORANGE, California
Brief Legal Description INT. LAMSON & WALNUT

Document Number 2005 - 0023



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/30/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/30/05

Signed Brace G. Hall L.S. or R.C.E. No. 4703




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 04 2005


and examined and filed JAN 19 2005

Signed Robert Jelinek L.S. or R.C.E. No. 6803



Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 1-A PG 83.


● = FD LTT "CITY OF GARDEN GROVE" PER RI

▲ = FD NEV BAR W/PM IN WELL PER RI.

○ = SET LTT LS0703.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM AND ARE SHOWN FOR CONVENIENCE

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0022Brief Legal Description 4117 EUCALYPTUS STREET & JERRY LANECounty of ORANGE, California

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/3/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See PAGE 2


A description of the physical condition of the monument as found and as set or reset:

See PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/3/04

Signed B.G.Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


JAN 04 2005

This Corner Record was received _____


and examined and filed JAN 19 2005

Signed Robert Jelinek L.S. or R.C.E. No. 6803

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



● = FD HEX BAR w/pins in well per RI 5.00' NORTH OF END.

RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 1 PAGE 748.

▼ = FD LEAD TACK & TAG "CITY OF GARDEN GROVE" PER RI

○ = SET LEAD TACK & TAG LS 4703

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.


CORNER RECORD

City of GARDEN GROVE

County of ORANGE, California

Brief Legal Description 5' NORTH OF E INT. LAMPSON AVE & EUCALYPTUS STREET

Document Number 2005-0021



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|--------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 12/3/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/3/05

Signed Robert Jelinek L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 04 2005


and examined and filed JAN 19 2005

Signed Robert Jelinek L.S. or R.C.E. No. 6803

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE TIC BOOK II PG 89.

() = RECORD PER RI


● = FD LTT "CITY OF GARDEN GROVE" PER RI

▲ = FD RR SPIKE W/DM IN WELL PER RI

○ = SET LTT LS 4743.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM AND ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

City of GARDEN GROVEBrief Legal Description E NW 1/4 EUCALYPTUS ST. & ALLEN DRIVEDocument Number 2005-0020County of ORANGE, California**CORNER TYPE**

Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/30/04**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/30/04.

Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received JAN 04 2005and examined and filed JAN 19 2005Signed Robert Jelinek L.S. or R.C.E. No. 6803Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 11 PG 90.

() = RECORD PER RI


▲ = FD RR SPKE W/PM IN WELL PER RI

● = FD LTT "CITY OF GARDEN GROVE" PER RI

○ = GET LTT LS 4703.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE

CORNER RECORD

City of GARDEN GROVEBrief Legal Description # 1157 EUCALYPTUS ST. & MARIAN DRIVEDocument Number 2005-0018County of ORANGE, California

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/3/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/3/05

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 04 2005
and examined and filed JAN 19 2005


Signed Robert Jelinek L.S. or R.C.E. No. 6803

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

NO SCHE



▲ = FD SPIKE & WASHER CS 5411

■ = FO L77 LS 541 N T.C.


O = SET CTT LS 4743 IN TC

● = FD MONGEMENT AS X'DTED.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATA(M).

CORNER RECORD

City of GARDEN GROVE Document Number _____
County of ORANGE, California
Brief Legal Description E INT. MAGNOLIA ST & MACALPINNE RD



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 4/12/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2

A description of the physical condition of the monument as found and as set or reset:
SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on JAN 13, 2007

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 5 PAGE 67.

() = RECORD PER RI

■ = FD S&W "CITY OF GARDEN GROVE" PER RI.

▲ = FD CONC. NAIL IN TC PER RI

● = FD LTT "CITY OF GARDEN GROVE RP" IN TC PER RI.


○ = SET LTT LS #743 IN TC

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM.

CORNER RECORD

Document Number 2006-1791City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description EC & JOYCE DRIVE EAST OF DESMOND ST

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 10/4/06

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on Nov. 26, 2006

Signed B. Hall L.S. or R.C.E. No. 4712

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOV 28 2006
 and examined and filed JAN 03 2007


Signed J. C. Hornecker L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

CORNER RECORD

Document Number 2006-1792City of Garden GroveCounty of Orange

, California

Brief Legal Description CLINT JOYCE DRIVE & DESMOND ST.

CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 10/4/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 25, 2006

Signed B. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOV 28 2006and examined and filed JAN 03 2007Signed J.C. Hornecker L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE NE BOOK 5 PG 66.

() = RECORD PER RI.

■ = FD S&W "CITY OF GARDEN GROVE" PER RI.

▲ = FD L77 "CITY OF GARDEN GROVE RP" IN TC PER RI.

● = FD LEAD & TACK IN TC PER RI

○ = SET L77 LS 4743 IN TC

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM.


CORNER RECORD

Document Number 2006 - 1793

City of GARDEN GROVE

County of ORANGE, California

Brief Legal Description JOYZELLE DRIVE 7' WEST OF DESMOND ST.



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 10/14/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Nov 13, 2006

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOV 28 2006

and examined and filed JAN 03 2007


Signed JON C. HORNECKER L.S. or R.C.E. No. 7212



Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

NO SCALE




RI = RECORD PER CITY OF GARDEN GROVE THE BOOK 5 PG 66.

() = RECORD PER RI

- = FD SAW "CITY OF GARDEN GROVE" PER RI.
- = FD LTT "CITY OF GG RP" IN TC PER RI.
- = FD LEAD & MARK IN TC PER RI.
- = SET LTT CS 4743 IN TC

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM

NO SCALE

RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 5 PG 66.

() = RECORD PER RI.

▲ = END. FD SHAFT OF SPIKE.

● = FD LEAD & STAK IN TC PER RI

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM.


CORNER RECORD

City of GARDEN GROVE

Brief Legal Description JOYCE Drive & HOMECOMING DRIVE

Document Number 2006-1794

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 10/4/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2.


A description of the physical condition of the monument as found and as set or reset:

SEE PG 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 13, 2006

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOV 28 2006


and examined and filed JAN 03 2007

Signed J.C. Hall L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

~~NO SOURCE~~

RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 5 PG 62.

() = RECORD PER RI

▲ = FD S&W "CITY OF GARDEN GROVE" PER RI.

● = FD LTT "CITY OF GG RP" PER RI IN T.C.

THE BEARINGS SHOWN HEREON ARE BASED UPON
AN ASSUMED DATUM


CORNER RECORD

City of GARDEN GROVE

Brief Legal Description PRC VOLZELLE DRIVE 190^{FT} EAST OF MAGNOLIA STREET

Document Number 2006-1795

County of ORANGE, Calif



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 10/14/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on NOV 13, 2006

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOV 28 2006


and examined and filed JAN 03 2007

Signed JON C. HORWECKER L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CORNER RECORD # 2003-259A.

() = RECORD PER RI.

● = FO LTT LS 5411 IN TC PER RI

○ = SET LTT LS 4743 IN TC.


◀ = FO SPIKE & WASHER LS 5411 per 2003-960

THE BEARING SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM.

CORNER RECORD

Document Number 2006-1797City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description JOYCE CT / DRIVE & MAGNOLIA AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 10/09/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 10/13/2006

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOV 28 2006


and examined and filed JAN 03 2007

Signed J.C. Hall L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

NO SCALE

R1 = RECD0 PRC CITY OF GARDEN GROVE
ME Book 5 PAGE 62.

() = RECD0 PRC R1.
 \triangle = SET CTT C.S. 0743 IN T.C.
 X = FD CHS. + IN T.C. PRC R1.
 \blacktriangle = FD CTT "CITY OF SG RP" PRC R1
 \bullet = FD CONC MAC IN T.C. PRC R1 UNLESS
 OTHERWISE NOTED

THE BEARING'S SHOWN HEREON ARE
BASED UPON AND ASSUMED DATA 1/4

CORNER RECORD


City of GARDEN GROVE

Document Number 2006-1796

County of ORANGE

, California

Brief Legal Description PRE JOYZELLE DRIVE 95' E/O MAGNOLIA
STREET.



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 10/14/06

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 13, 2006

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


NOV 28 2006

This Corner Record was received _____


and examined and filed JAN 03 2007

Signed J.C. Hall L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____




● = FD CALTRANS 2 1/2" of BRASS CAP w/PM IN WELL PER
CR # ~~2003-244A~~ DN 1.1.

R1 = RECORD PER CR # 2003-244A

() = RECORD PER R1

▲ = FD LTT "GARDEN GROVE SURVEY" IN TC PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED
DATUM



● = FD CACTRANS 2½" Ø ENASS CAP W/PM IN WELL PER
CR # ~~2003~~ 2003-244A ~~DN 1.1~~ DN 1.1!

R1 = RECORD PER CR # 2003-244A

C) = RECORD PER R1


▲ = FD LTT "GARDEN GROVE SURVEY" IN TC PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED
DATUM

CORNER RECORD

Document Number 2007-0410City of GARDEN GROVECounty of ORANGE


, California

Brief Legal Description EINT. GARDEN GROVE BLVD & WILSON ST.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/25/07**COORDINATES (Optional)**

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elevation _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey


Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/25/07Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**MAR 01 2007

This Corner Record was received _____

examined and filed APR 13 2007Signed J. C. Hohnecker P.L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____


CORNER RECORD

City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description E.I.T. GARDEN GROOVE BLVD & WILSON ST.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/25/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/25/07Signed B. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



RI = RECORD PER COPIER RECORD 2003-947B


() = RECORD PER RI

● = FD SAW LS 5011 PER RI

▼ = FD LTT "GARDEN GROVE SURVEY" IN TC PER RI.

= FD LTT LS 5011 IN TC PER RI

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.



R1 = RECORD PER CORNER RECORD 2003-947B

() = RECORD PER R1

● = FD SDW LS 5411 PER R1

▼ = FD LTT "GARDEN GROVE SURVEY" IN TC PER R1.

■ = FD LTT LS 5411 IN TC PER R1


THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

Document Number 2007-0407City of GARDEN GROVECounty of ORANGE

California

Brief Legal Description

2117 GARDEN GROVE BLVD & LOUISE STREET

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation. _____
 Vertical Datum: NGVD29 NAVD88
 Units: Metric Imperial U.S. Survey

Date of Survey 2/25/07Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on 2/25/07

Signed B. HALL P.L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received MAR 01 2007
 APR 13 2007

examined and filed

Signed J.C. HALL P.L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment

CORNER RECORD

City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description 1117 GARDEN GROVE BLVD & LOUISE STREET**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/25/07**COORDINATES (Optional)**

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elevation. _____

Vertical Datum: NGVD29 NAVD88 Units: Metric Imperial U.S. Survey Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/25/07

Signed B. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



RI = RECORD PER CORNER RECORD 2003-9288


() = RECORD PER RI

■ = FD 9K & WASHED LS 5011 PER RI

● = FD LT7 "GARDEN GROVE SURVEY" N TC PER RI.

▼ = FD LT7 LS 5011 IN TC PER RI

THE BEARINGS SHOWN HEREON ARE BASED UPON AN
ASSUMED DATUM.



RI = RECORD PER CORNER RECORD 2003-9288

() = RECORD PER RI


■ = FD PK & WASHER LS 5411 PER RI

● = FD LT7 "GARDEN GROVE SURVEY" NTC PER RI.

▼ = FD LT7 LS 5411 IN TIC PER RI

THE BEARINGS SHOWN HEREON ARE BASED UPON AN
ASSUMED Datum.

CORNER RECORD

Document Number 7007-0408City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description 2117 GARDEN GROVE BLVD & LORNA ST.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/05/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/25/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 9743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 01 2007

examined and filed APR 13 2007

Signed JON C. HORNECKER P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____


CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE

, California

Brief Legal Description INT GARDEN GROVE BLVD & LORNA ST.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/25/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/25/07

Signed BRUCE G. HALL P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

~~NO SCALE~~


R1 = RECORD PER CITY OF GARDEN GROVE TIE BOOK 4
PAGE 126

() = RECORD PER R1

- = FD PK NAIL NO REF. ACC AS & INT. TO BE DESTROYED.
- = FD LT "GARDEN GROVE SURVEY" IN TC PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED
DATUM.

NO SCHE



R1 = RECORD PER CITY OF GARDEN GROVE TIE BOOK 4
PAGE 126

(C) = RECORD PER R1

■ = FD PK NAIL NO REF. ACC AS & INT. TO BE DESTROYED.


● = FD LTT "GARDEN GROVE SURVEY" IN TC PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED
DATUM.

CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of Orange, California
Brief Legal Description INT OF GARDEN GROVE BLVD &
JOSEPHINE STREET**CORNER TYPE**

Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/25/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
SEE PG 2.A description of the physical condition of the monument as found and as set or reset:
SEE PG 2.**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/25/07Signed B. Kelly P.L.S. or R.C.E. No. 9703**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____


Title _____

County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVEDocument Number 2007-0409County of ORANGE

, California

Brief Legal Description CINT OF GARDEN GROVE BLVD &
JOSEPHINE STREET

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 2/25/07

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation. _____
 Vertical Datum: NGVD29 NAVD88
 Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PG 2


A description of the physical condition of the monument as found and as set or reset:

SEE PG 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/25/07Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 01 2007examined and filed APR 13 2007Signed Jon C. Hornecker P.L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____




- = FD CUT SPIKE WITH PM, FLUSH, NO REF. ACC AS E GROVEVIEW ST. & RADIUS POINT.
- = FD LCT PER CITY OF GARDEN GROVE TIES FOR TRACT NO. 3799 IN T.C.
- △ = SET LTT LS #703 IN CONC WALK UNLESS OTHERWISE NOTED.
- () = RECORD PER CITY OF GARDEN GROVE TIES FOR TRACT NO. 3799

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM.

✓ STANFORD AVE.

110 Seite



- = FD CUT SPIKE WITH PM, FLUSH, NO REF. ACC AS & GROVEVIEW ST.
& RADIUS POINT.
 - = FD LET PER CITY OF GARDEN GROVE TIES FOR TRACT NO. 3799
IN T.C.
 - △ = SET LTT LS 4743 IN CONC. WALK UNLESS OTHERWISE NOTED.
 - () = RECORD PER CITY OF GARDEN GROVE TIES FOR TRACT NO. 3799


THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

Document Number _____

City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description GROVEVIEW STREET RADUS POINT**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey Nov 24, 2006**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PAGE 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2.**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Dec 3, 2006

Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

TB № 15

PAGE No 53A


INTERSECTIONS

CITY OF GATED GROVE


TRACT 3799

VOCHEIS
TRINDE
NELSON INC.

ALL POINTS
VERIFIED
6-19-62
W.J.M.



CORNER RECORD

City of GARDEN GROVEDocument Number 2006-1810County of ORANGE, CaliforniaBrief Legal Description GROVEVIEW STREET RADIUS POINT.

CORNER TYPE

Government Corner

 Control

Meander

 Property

Rancho

 Other Date of Survey Nov 24, 2006

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial U.S. Survey foot Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:


SEE PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Dec 3, 2006Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2006and examined and filed JAN 03 2007Signed Jon C. Hornecker L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

CORNER RECORD


City of Garden Grove

Brief Legal Description E MORNOLIA ST. AT NORTH LINE TRACT NO

5296 MM 89/45-46

Document Number 2007-0003 A

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input checked="" type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 12/27/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83 _____
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2.

A description of the physical condition of the monument as found and as set or reset:


SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/27/06

Signed Bruce G. Hall

L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 12 2007


and examined and filed MAY 14 2007

Signed J. C. Hornecker L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

2007-0003 A



CORNER RECORD

City of GARDEN GROVEDocument Number 2006-1809Brief Legal Description at SHERLOCK CIRCLE AT cul -DE- SAC.County of ORANGE, California

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 11/24/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Dec 3, 2006

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2006


and examined and filed JAN 03 2007

Signed J.C. Hornecker L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

~~NO SCALE~~


- = FD CUT SPIKE WITH P.M. NO REF. ACC. AS SHERLOCK CIRCLE & RADIUS POINT.
- = FD LEAD & TACK IN T.C. PER CITY OF GARDEN GROVE TIES FOR TRACT NO 5296
- () = RECORD PER CITY OF GARDEN GROVE TIES FOR TRACT NO 5296.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of Garden Grove

Document Number _____

County of Ocana, CaliforniaBrief Legal Description at SHERLOCK CIRCLE AT CUL - DE - SAC.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 11/24/06**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Dec 3, 2006

Signed B. Hall L.S. or R.C.E. No. 4743

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

TIE NOTES FOR TRACT 5296
CITY OF GARDEN GROVE

Apr 28, 1964


STAPLES ENGINEERING CO.
12311 CHAPMAN AVE
GARDEN GROVE, CALIF.
534-0195 SUITE 117

Clayton P. Staples
RCE 1165

FD CUT SPKES
W/P.M.

Heacock.


No scale



L&T denotes Lead and Tack
in curb.

$Pk \& T$ denotes Pk spike
and Tm .


NO SCALE



- = FD CEE SPIKE WITH P.M. NO REF. ACC. AS SHERLOCK CIRCLE & RADIUS POINT.
- = FD LEAD & TACK IN T.C. PER CITY OF GARDEN GROVE TIES FOR TRACT NO 5296
- () = RECORD PER CITY OF GARDEN GROVE TIES FOR TRACT NO 5296.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of GARDEN GROVECounty of ORANGE, California
Brief Legal Description 8117 MAGNOLIA STREET & SHERLOCK
CIRCLEDocument Number 2007-0002 A

CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 12/26/06

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83 _____
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88 _____
 Meas. Units: Metric Imperial
 U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/30/06Signed B. HallL.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT


JAN 12 2007

This Corner Record was received _____

and examined and filed MAY 14 2007Signed J.C. HauseL.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

0000



- ▲ = INT. FO PK & CITY OF GARDEN GROVE SURVEY DEPT. MASNER
~~RECORDED~~ PER CITY OF GG THE BOOK NO. 8 PG 82.
- = FO L77 LS SAIL IN TC NO ~~800~~. PER CR 2007-0105
- = FO LEAD & TACK IN TC PER THE NOTES FOR TRACT NO. 5296 AT THE CITY OF GARDEN GROVE.
- () = RECORD PER THE NOTES FOR TRACT NO. 5296
- [] = RECORD PER CR 2007-0105

THE 2000 ft. 25' surveyed distance area based upon an assumed


CORNER RECORD

City of GARDEN Grove

Brief Legal Description 6 MAGNOLIA STREET A7 SOUTH TRACT BOUNDARY
TRACT NO. 5296 MM 89/45-46.

Document Number 2007-0001 A

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input checked="" type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 12/27/06

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83 _____
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88 _____
 Metric Imperial
 Meas. Units: U.S. Survey fox

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner
SEE PG 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on 12/20/06

Signed Bruce G. Hall L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 12 2007

and examined and filed MAY 14 2007


Signed John C. Hornecker L.S. or R.C.E. No. 7212
 Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

SHERLOCK CIRCLE

FD PER CITY OF GG THE BOOK
NO. 8 PG 82




THE COORDINATES SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

Document Number 2007-0411City of Garden GroveCounty of Orange

, California

Brief Legal Description at GARDEN GROVE BLVD. S18.6° WEST OF
E HASLER STREET.

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

COORDINATES (Optional)


N. _____
 E. _____
 Zone NAD27 NAD83
 NAD83 Epoch _____
 Elevation. _____
 Vertical Datum: NGVD29 NAVD88
 Units: Metric Imperial U.S. Survey

Date of Survey 1/26/07Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on 2/25/07Signed B.G.Hall P.L.S. or R.C.E. No. 4743


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 01 2007examined and filed APR 19 2007Signed J.C. Hornscher P.L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

NO SCALE

DRAFTS 57



R1 = RECORD PER CORNER RECORD 2003-938B


() = RECORD PER R1

▼ = FD PK & WASHER LS 5411 PER R1

● = FD LTT LS 5411 IN TC PER R1

THE BEARINGS SHOWN HEREON ARE BASED UPON AN
ASSUMED DATA

CORNER RECORD

Document Number 2007-0412City of Garden GroveCounty of Ocgt/6C, CaliforniaBrief Legal Description 6 Garden Grove Blvd 330' WEST OF E
1st Street.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Date of Survey 1/26/07Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/25/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 01 2007examined and filed APR 19 2007Signed J.C. Hall P.L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



R1 = RECORD PER CORNER RECORD 2003-9388.


() = RECORDED PER R1

▲ = FD PK & WASHER LS 5411 PER R1

● = FD UTT LS 5411 IN TC PER R1

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of GARDEN GROVEBrief Legal Description 8 BEEFAST DRIVE 212' EAST OF E DONOGHUE DRIVEDocument Number 2007-0191 ACounty of ORANGE, California

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/15/07

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch.
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/17/07Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received JAN 30 2007
and examined and filed MAR 05 2007Signed J.C. Hornecker L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

NO SCALE

Z

EDENICAL DANE



- R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK 11 PAGE 95
R2 = RECORD PER MONUMENT TIES FOR TRACT NO. 5037 MM 195/45-46
ON FILE AT THE CITY OF GARDEN GROVE,
() = RECORD PER REFERENCE NO 7 C.D.
● = FD LEAD & JACK IN TC PER R1 & R2.
◎ = FD LTT CITY OF GARDEN GROVE SURVEY "IN TC PER R1
▲ = FD PK & BRASS TAG "CITY OF GARDEN GROVE SURVEY" PER
R1 DOWN O.Z.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN
ASSUMED DATUM.


CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE

, California

Brief Legal Description E BEEFAST DRIVE 212^{1/2} FT EAST OF E DONEGAL DRIVE**CORNER TYPE**Government Corner Control Meander Property Rancho Other Date of Survey 1/15/07**COORDINATES (Optional)**

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____


Elev. _____

Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial U.S. Survey foot Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/17/07Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received _____
and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK II PAGE 95.

R2 = RECORD PER MONUMENT TIES FOR TRACT NO. 5037 MM 195/45-46
ON FILE AT THE CITY OF GARDEN GROVE.

() = RECORD PER REFERENCE NOTCD.


(●) = FD LEAD & JACK IN TC PER R1 & R2.

(○) = FD LTT CITY OF GARDEN GROVE SURVEY "IN TC PER R1

(▲) = FD PK & BRASS TAG "CITY OF GARDEN GROVE SURVEY" PER
R1 DOWN 0.2.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN
ASSUMED DATUM.

CORNER RECORD

City of Garden GroveDocument Number 2007-0193 ACounty of Orange, California
Brief Legal Description 2117 BREAKFAST DRIVE & DONIGAL DRIVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other


Date of Survey 1/15/07

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/17/07Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 30 2007and examined and filed MAR 05 2007Signed Jon C. Hornecker L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE THE BOOK 11 PG 94.

() = RECORD PER RI

● = FD LEAD & TACK IN TC PER RI.


○ = SET LEAD TACK & TAG LS 4743 IN TC.

▲ = FD INTERSECTION OF 4 SPIKE & WASHERS LS 4743
TANGENT OVER TIES PER RSB 210/2.

CORNER RECORD

City of GARDEN GROVE

Document Number _____

Brief Legal Description 2117 BELFAST DRIVE & DOUGAL DRIVECounty of ORANGE, California**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 11/15/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 11/17/07Signed Bruce G. HallL.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE ZIC BOOK H PG 94.


() = RECORD PER RI

• = FD LEAD & TACK IN TC PER RI.

○ = SET LEAD MARK & TAG LS 4743 IN TC.

▲ = FD INTERSECTION OF 4 SPIKE & WASHERS LS 4743
TANGENT OVER ZICS PER RSB 210/2.

CORNER RECORD

City of Green GablesBrief Legal Description 6 BELFAST DRIVE 17 1/2 NW OF 6 GALWAY STREET.Document Number 2007-0190 ACounty of ORANGE, California

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/15/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1-18-07

Signed Bruce G. Hall L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 30 2007
and examined and filed MAR 05 2007

Signed [Signature] L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE THE BOOK II PG 97.

() = RECORD PER RI

▲ = FD REMAINS OF SPIKE IN LIEU OF PK & TAG "CITY OF GARDEN GROVE" PER RI, DN O. d.


● = FD LEAD & TACK IN T.C. PER RI

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of GARDEN GROVE


Document Number _____

County of ORANGE, California
Brief Legal Description INT. GALWAY STREET & BEAFAST DRIVE**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/15/07**COORDINATES (Optional)**

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/15/07Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK # 96-76

() = RECORD PER R1

● = FD LT "CITY OF GARDEN GROVE" IN TC PER R1 UNLESS OTHERWISE NOTED.


▲ = FD INTERSECTION OF 4-# MAG NAIL TIES, NO REF. FITS TIES PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of GARDEN GROVEDocument Number 2007-0195 ACounty of ORANGE

, California

Brief Legal Description INT. GALWAY STREET & BERFASY DRIVE

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/15/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2

A description of the physical condition of the monument as found and as set or reset:
SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/17/07

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 30 2007


and examined and filed MAR 05 2007

Signed Jon C. Hornecker L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK II PG 96


() = RECORD PER RI

● = FD LTT "CITY OF GARDEN GROVE" IN TC PER RI UNLESS OTHERWISE NOTED.

▲ = FD INTERSECTION OF 4-FO MAG NAIL TIES, NO REF. FITS TIES PER RI.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM

CORNER RECORD

City of Garden GroveCounty of Orange, CaliforniaBrief Legal Description E. BELFAST DRIVE 42.46' NW OF E GALWAY S**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/15/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot


Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PAGE 2A description of the physical condition of the monument as found and as set or reset:
SEE PAGE 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/18/07Signed B.G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**

JAN 30 2007

This Corner Record was received _____

and examined and filed MAR 05 2007Signed J.C. Hornecker L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE THE BOOK 11 PG 96.

() = RECORD PER RI


● = FD LTT "CITY OF GARDEN GROVE" IN TC PER RI UNLESS OTHERWISE NOTED.

▲ = FD PK & BRASS TAG "CITY OF GARDEN GROVE" PER RI DOWN O.Z!

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

Document Number _____

City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description # BELFAST DRIVE 42.46' NW OF # GALWAY ST.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/15/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/18/07

Signed Bruce G. Hall L.S. or R.C.E. No. 4743

**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE THE BOOK - II PG 96.

() = RECORD PER RI


● = FD LTT "CITY OF GARDEN GROVE" IN TC PER RI UNLESS OTHERWISE NOTED.

▲ = FD PK & BRASS TAG "CITY OF GARDEN GROVE" PER RI DOWN O.Z.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATA.

CORNER RECORD

Document Number _____

City of Green Grove County of Orange, California
Brief Legal Description E BELFAST DRIVE 17' E NW OF E GALWAY STREET.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/15/07**COORDINATES (Optional)**

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1-18-07Signed B. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



R1 = RECORD PER CITY OF GARDEN GROVE TIE BOOK II PG 97.


() = RECORD PER R1

▲ = FD REMAINS OF SPIKE IN LIEU OF PK & TAG "CITY OF GARDEN GROVE" PER R1, DN 0.4'.

● = FD LEAD & JACK IN T.C. PER R1

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM

CORNER RECORD

City of GARDEN GROVEDocument Number 2007-0192 ABrief Legal Description 2117 GARDEN GROVE BLVD & DUNGAN LANECounty of ORANGE, California

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/17/07

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/17/07

Signed Brace Hall

L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 30 2007
and examined and filed MAR 05 2007

Signed JCH L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



R1 = CITY OF GARDEN GROVE ZIE BOOK 3 PAGE 44

● = FD CTT "CITY OF GARDEN GROVE SURVEY" AT TL. PER R1.

▲ = FD SPKE & WASHER "CITY OF GARDEN GROVE SURVEY"
PER R1.

() = RECORD PER R1.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN
ASSUMED DATUM.


CORNER RECORD

City of Garden Grove

Document Number _____

County of Orange, California

Brief Legal Description

INT GARDEN GROVE BLVD & DUNGAN LANE**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/17/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PG 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2.**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 1/17/07

Signed B. J. Hall

L.S. or R.C.E. No. 4743

**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



R1 = CITY OF GARDEN GROVE TIE BOOK 3 PAGE 84.

● = FD LTT "CITY OF GARDEN GROVE SURVEY" IN TL. PER R1,

▲ = FD SPKE & KASPER "CITY OF GARDEN GROVE SURVEY"
PER R1.

() = RECORD PER R1.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN
ASSUMED DATUM.

FD PK & WASHER LS 5411
FLUSH PER CENTER RECORDED
2003-941B


C LAIRD ST.

NO SCALE

TRACT NO 2519
MM 79/20-21

S SET LTY LS 4743
IN T.C. TYPICAL

E GARDEN GROVE BLVD



() = RECORD PER TRACT NO. 2519 MM 79/20-21


▲ = FD MONUMENT AS NOTED.

○ = SET LTY LS 4743 IN T.C.

THE BEARINGS SHOWN HEREON ARE BASED UPON
AN ASSUMED DATUM

CORNER RECORD

City of GARDEN GROVE Document Number _____
County of ORANGE, California
Brief Legal Description E GARDEN GROVE BLVD 110' WEST OF
E CARDO STREET.



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/17/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2

A description of the physical condition of the monument as found and as set or reset:
SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/17/07

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____


Title _____

County Surveyor's Comment _____

CORNERS RECORDED

Document Number 2004-1661City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description SE CAMPSON AVE. 1125 FT EAST OF SE MAGNOLIA ST.

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 12/1/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on 1/27/04


Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 22 2004and examined and filed AUG 03 2004Signed Michael K. Sullivan L.S. or R.C.E. No. LS. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____


TRACT N/C 1155
MAY 30/26



ALL DISTANCES ARE MTR PER CR 2004-1261

Z, NO SCALE

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0931BCounty of ORANGE, CaliforniaBrief Legal Description EL CAMINO AVE. 1125 FT E / & MAGNOLIA ST.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/30/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on JULY 5, 2005

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 13 2005

AUG 18 2005

and examined and filed AUG 18 2005

Signed J. C. Bush L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

TRACT NO
1862 MM 537/20-22

REC. PER TR 12520
1124 59"

ELAMSON AVE

TRACT NO 158

MM 36/26

FD GGD SPKE

DW 035 NO REF
ACCEPTED IN LI CU OF

S/N LS2681 PER TR12520

Z NO SECT

SECTIONAL
SECTION LINE


LEGEND

- = FD LEAD TACK & TAG LS 2681 IN T.C. NO REF. UNLESS OTHERWISE NOTED
- ▷ = SET LEAD TACK & TAG LS 3703 IN T.C.

CORNER RECORD

Document Number 2004-1262City of Garden GroveCounty of ORANGE

, California

Brief Legal Description 9 CAMPSON AVE AT EAST LINE TRACT NO 1250
MM 572/05-44

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 12/1/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on 1/27/04

Signed Bruce G. HallL.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 22 2004and examined and filed AUG 02 2004Signed Michael K. Sullivan - L.S. or R.C.E. No. LS. 6254Title DEPUTY COUNTY SURVEYOR


County Surveyor's Comment _____

EMERSON ST.
SET MARK LINE

TRACT NO 12520
M.V. 532/45-46

PMB 152/11-12

NO SCALE



O = SET SAW LS 4743

● = FD LTT LS 2681 IN TL PER CR 2004-1262

ALL DIST. ARE MGR PER CR 2004-1262


CORNER RECORD

City of GARDEN GROVE

Brief Legal Description 6 LAMSON AVE AT EAST LINE TRACT NO. 12520
MM 592/45-46

Document Number 2005-0930B

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input checked="" type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 12/30/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PL 2

A description of the physical condition of the monument as found and as set or reset:

SEE PL 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on MAY 5, 2005

Signed B. HALL L.S. or R.C.E. No. 2743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 13 2005


and examined and filed AUG 18 2005

Signed J. C. HALL L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

CHAMBERS 52 (Sector Line)




● = FD SPIKE, WASHED STAG LS 2681 PER TRACT NO 12520 DA 0.25

▲ = FD LEGD, STAG 26746 LS 2681 IN T.C., NO RET.

City of GARDEN GROVECounty of ORANGE

California

Brief Legal Description West Line Tract No 1250, MM 592/05446 A7
E. CAMERON AVE

CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other

Date of Survey 12/1/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action 1/27/04Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 22 2004and examined and filed AUG 02 2004Signed Michael K. Sullivan L.S. or R.C.E. No. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____




CORNER RECORD

Document Number 2005-0929B

City of Green Groves

County of DODGE, California

Brief Legal Description WEST LINE TRACT NO 12520, MM 592/25-46 A7
& LAMSON AVE.



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input checked="" type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 12/30/04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:


SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JULY 5, 2005

Signed B. Hall L.S. or R.C.E. No. 2743



COUNTY SURVEYOR'S STATEMENT

JUL 13 2005

This Corner Record was received _____


and examined and filed AUG 18 2005

Signed J. C. Hatch L.S. or R.C.E. No. 7212


Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



- = FO GEAR HEAD SPLINE & WASHER, ILLEGIBLE, DN 020, NO REF.
ACCEPTED IN LIEU OF S/W LS 2681 PER TR 12520
- ▼ = FO LEAD JACK #7AG LS 2681 IN T.C. NO REF.




- △ FD PUNCH BAR IN WELL MAN, FITS TIES PER CITY GG TB #2 PG 121A
- FD LATG (GG SURVEY) PER CITY GG TB #2 PG 121A
▲ TO BE DESTROYED
- SET LATG LS 7707 AT BK S/W
- FD CH 'X' PER CITY GG TB #2 PG 121A, RETAGGED LS 7707
- FD LAT (NO REF) RETAGGED LS 7707

NOTE: THESE TIES ARE FOR THE
PURPOSE OF PERPETUATING THE
FOUND MONUMENTATION. NO CLAIM
IS MADE AS TO THE RELATIONSHIP OF
THE POINTS OR LINES SHOWN HEREON
TO THE TRUE BOUNDARY LOCATIONS.

CORNER RECORD

Document Number _____

City of GARDEN GROVECounty of GRANGE, CaliforniaBrief Legal Description 4 INT GARDEN GROVE BLVD + MAGNOLIA ST

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey APRIL 21, 06

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

FD WELL MON @ APPARENT 4 INT. FD TIES AS NOTED
PER CITY OF GARDEN GROVE TB NO. 2 PG 121A. FD
ADDITIONAL TIES NO REF.

A description of the physical condition of the monument as found and as set or reset: SET NEW

TANGENT TIE & RETAGGED XSTG TIES AS NOTED PRIOR
TO CURB REMOVAL.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on JULY 23 2006Signed Walter F. Lundin L.S. or R.C.E. No. 7707


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____
and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____




- = FO MONUMENT AS NOTED
- = SET LEAD JACK & TAG LS #743 INT.C
- () = RECORD PER REF. NOTED
- THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE ONLY.

CORNER RECORD

Document Number 2005-0650ACity of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description E GARDEN GROVE BLVD-HARCOR BLVD. 1634^{1/2} NORTH
OF 7TH ST AVE.

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 3/6/05

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 4/19/05

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 28 2005

and examined and filed MAY 25 2005

Signed L.S. or R.C.E. No. 6185

Title COUNTY SURVEYOR




County Surveyor's Comment

CORNER RECORD

Document Number _____

City of GARDEN GROVECounty of ORANGE

California

Brief Legal Description SHARBOR BLVD AS' T NORTH OF E FLAGSTONE AVE.**CORNER TYPE**

Government Corner

 Control

Meander

 Property

Rancho

 Other

Date of Survey

3/6/05**COORDINATES (Optional)**

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____


Elev. _____

Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial U.S. Survey foot Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 4/20/05Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



● = FD MONUMENT AS NOTED.


○ = SET LTT LS 4703 IN T.C.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

Document Number 2005-06494City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description E HARBOR BLVD 45' E NORTH OF E FLAGSTONE AVE.

CORNER TYPE

Government Corner Control Meander Property Rancho Other Date of Survey 3/6/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 4/20/05

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

APR 28 2005

This Corner Record was received _____


and examined and filed MAY 25 2005

Signed Raymond L. Mathe L.S. or R.C.E. No. 6185

Title COUNTY SURVEYOR



County Surveyor's Comment _____



● = FD MONUMENT AS NOTED.

○ = SET LT 7 LS 4703 IN T.C.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.

CORNER RECORD


Document Number 2005-0648A

City of GARDEN GROVE

County of ORANGE

, California

Brief Legal Description HARBOR BLVD 108TH NORTH OF & FLAGSTONE AVE



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input checked="" type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 3/6/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 1/19/05

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

APR 28 2005

This Corner Record was received _____

and examined and filed MAY 25 2005


Signed R. Mathe L.S. or R.C.E. No. 6185

Title COUNTY SURVEYOR



County Surveyor's Comment _____

MAY BE REPRODUCED
BY CONSTRUCTION



○ = SET LTT LS 4743 IN TC

● = FD LTT LS 6161 IN TC UNLESS OTHERWISE NOTED.
NO REF.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.


CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE, California

Brief Legal Description E INT Harbour Blvd & Flagstone Ave.



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3-06-05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See Page 2


A description of the physical condition of the monument as found and as set or reset:

See Page 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action April 20, 2005

Signed Bruce G. Hall L.S. or R.C.E. No. 0703




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____
and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



- = SET L77 LS 4703 IN TC
- = FD L77 "CITY OF GARDEN GROVE" IN TC PER CITY OF GG THE BOOK 11 PG 32 UNLESS OTHERWISE NOTED.
- () = RECORD PER CITY OF GG TB 11 PG 32.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.


CORNER RECORD

City of GARDEN GROVE

County of ORANGE, California

Brief Legal Description E INT HACONNE BLVO & FLAGSTONE AVE.

Document Number 2005-0647A



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3-06-05

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See Page 2

A description of the physical condition of the monument as found and as set or reset:

See Page 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Action April 20, 2005

Signed Ex-Officio

L.S. or R.C.E. No. 0703



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 28 2005


and examined and filed MAY 25 2005

Signed Ex-Officio L.S. or R.C.E. No. 6185

Title COUNTY SURVEYOR



County Surveyor's Comment _____



THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.

GILBERT STREET

MAY BE DESTROYED
BY ADA RAMP
CONSTR

TO "ON TRAITS" REASS
OPEN W/PIN PER CITY
OF GG T.B. 2 PG 124A
IN WELL

N $49^{\circ} 55' 23''$ W 73.045'
(73.049)
N $60^{\circ} 23' 46''$ W 85.53'

N $58^{\circ} 18' 45''$ E 72.65'
(72.57)

E GARDEN GROVE
BC 413

N $54^{\circ} 13' 09''$ E 72.36'
(72.45')

N $57^{\circ} 30' 03''$ W 78.665'
(69.3) 60.36'

GILBERT STREET



MAY BE DESTROYED
BY ADA RAMP
CONSTRUCTION

LEGEND

- = FD MON. AS NOTED
- ▲ = FD LTT "CITY OF GARDEN GROVE" IN T.C. PER CITY OF GARDEN GROVE TIE BOOK 2 PAGE 124A.
- = SET LTT LS 4743 IN T.C.
- () = RECORD PER CITY OF GG T.B. 2 PG 124A.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE ONLY.

GILBERT STREET

MAY BE DESTROYED
BY ADD RAMP
CONST.

N29°55'23" W 73°00'05"
(7309)

N60°23'46" N 85.53'

GRS 3000
FD ON THIS "PESS"
OF GARDEN GROVE
TIE BOOK 2 PG 124A

N58°18'05" E 72.655
(72.51)

E GARDEN GROVE
BL 412

N54°13'09" E 72.316
(72.45)

H13°21'22" E 78.53

N57°30'03" W 78.665
(69.37)

WILL BE DESTROYED
BY ADD RAMP
CONSTRUCTED

GILBERT STREET

LEGEND

- = FD MOW AS NOTED
- ▲ = FD LTT "CITY OF GARDEN GROVE" IN T.C. PER CITY OF GARDEN GROVE TIE BOOK 2 PAGE 124A.
- = SET LTT LS 4743 IN T.C.
- () = RECORD PER CITY OF GG T.B. 2 PG 124A.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE ONLY.


City of GARDEN GROVE

County of ORANGE

, California

Brief Legal Description

4 GARDEN GROVE BLVD AT GILBERT STREET



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/10/05

COORDINATES (Optional)

N. 2229544.537

E. 6039913.320

Zone V1 NAD27 NAD83

NAD83 Epoch 1991.35

Elev.

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/27/05

Signed Brace Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

APR 11 2005

This Corner Record was received APR 11 2005

and examined and filed MAY 9 2005

Signed P L.S. or R.C.E. No. 6185

Title COUNTY SURVEYOR



County Surveyor's Comment _____


CORNER RECORD

City of GARDEN GROVE

Brief Legal Description at GARDEN GROVE BLVD AT GILBERT STREET

Document Number _____

County of ORANGE, California



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/10/01

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/27/01

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

CORNER RECORD


City of Garden Grove

Brief Legal Description S/1 ACRES. GARDEN GROVE BLVD & GILBERT STREET

Document Number CR 2005-0651

County of Orange

, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/22/05

Signed BRUCE G. HALL

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 28 2005

and examined and filed SEP 12 2005

Signed J.C. HORNNECKER

L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment

E GARDEN GROVE BLVD

FD LTT "CITY OF GARDEN GROVE" IN
TC SEE CITY OF GG TB 2 PG 120A

FD "CAL TRANS" BRASS
CAP W/PAINTER
CITY OF GG TB 2
PG 120A IN WELL

N 58° 13' 49" E 72.36'

N 68° 40' 23" E 65.93'

N 65° 46' 00" E 68.80'

N 3° 02' 22" E 28.53'

NO SCALE

FD LTT LS 5508
IN WALL NO REF.

*SET LTT LS
6703 IN TC*

THE BEARINGS SHOWN HEREON ARE BASED
UPON AN ASSUMED DATUM.

*GILBERT
STREET.*

CORNER RECORD


City of GARDEN GROVE

Document Number _____

County of ORANGE

, California

Brief Legal Description _____

**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/10/05**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/27/05Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

E GARDEN GROVE BLVD

FD LTT "CITY OF GARDEN GROVE" IN
TC DEP CITY OF GG TB 2 PG 120A

FD "CAL TRANS" BRASS
CAP W/PM PER
CITY OF GG TB 2
PG 120A IN WELL

NO SCALE

FO LTT LS 5508
IN WALK

N 63° 54' 15" W
17.53

N 47° 10' 10" W
17.705

N 39° 09' 37" W
18.635

N 54° 13' 49" E
72.36

N 48° 00' 23" E
65.93

N 25° 46' 00" E
68.80


N 13° 01' 22" E
28.53

SET LTT LS
4703 IN TC

GILBERT
STREET.

THE BEARINGS SHOWN HEREON ARE BASED
UPON AN ASSUMED DATUM.

CORNER RECORD

Document Number 2005-0469ACity of GARDEN GROVE County of ORANGE, CaliforniaBrief Legal Description E INT. GARDEN GROVE BLVD & GALWAY STREET

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 3/27/05

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on 3/27/05

Signed B. Hall L.S. or R.C.E. No. 4703

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 11 2005and examined and filed MAY 9 2005Signed R. Mathe L.S. or R.C.E. No. 6185Title COUNTY SURVEYOR

County Surveyor's Comment _____



● = FO "CAL TRANS" SURVEY MONUMENT IN WELL PER CITY OF GARDEN GROVE TIE BOOK 2 PG 126B.

▼ = FO LTT "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 2 PG 126B

△ = SET LTT LS 4743 IN T.C.

() = RECORD PER CITY OF GG TIE BOOK 2 PG 126B.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM AND ARE SHOWN FOR CONVENIENCE.


CORNER RECORD

City of GARDEN GROVE

Brief Legal Description E INT. GARDEN GROVE BLVD & GALWAY STREET

Document Number _____

County of ORANGE, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch. _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/27/05

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

LEGEND


- = FO "CALTRANS" SURVEY MONUMENT IN WELL PER CITY OF GARDEN GROVE TIE BOOK 2 PG 126 B.
- ▼ = FO LTT "CITY OF GARDEN GROVE" PER CITY OF GG TIEBOOK 2 PG 126 B
- ▷ = SET LTT LS 4743 IN T.C.
- () = RECORD PER CITY OF GG TIE BOOK 2 PG 126 B.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM AND ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0468ACounty of ORANGE

, California

Brief Legal Description E GARDEN GROVE BLVD. 155'± WEST OF E
GATEWAY STREET

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/27/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 3/27/05Signed BRUCE G. HALL L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 11 2005and examined and filed MAY 9 2005Signed RAYMOND L. MATHE L.S. or R.C.E. No. 6185Title COUNTY SURVEYOR

County Surveyor's Comment _____



LEGEND

- = FD MON. AS NOTED
- ▲ = FD LTT "CITY OF GARDEN GROVE" IN T.C. NO REF.
- = SET LTT LS 4743 IN T.C.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE ONLY.


CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE, California

Brief Legal Description # GARDEN GROVE BLVD 155' WEST OF #
GATEWAY STREET



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on 3/27/05

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



LEGEND


- = FD MOW. AS NOTED
- ▲ = FD LTT "CITY OF GARDEN GROVE" IN T.C. NO REF.
- = SET LTT LS 4743 IN T.C.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE ONLY.

CORNER RECORD

Document Number 2005-0470 ACity of GARDEN GROVECounty of ORANGE

California

Brief Legal Description EINT. GARDEN GROVE BLVD & KERRY STREET.

CORNER TYPE

Government Corner

 Control

Meander

 Property

Rancho

 Other Date of Survey 3/27/05

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial U.S. Survey foot Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/27/05Signed Bruce G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 11 2005and examined and filed MAY 9 2005Signed R. Mathe L.S. or R.C.E. No. 6185Title COUNTY SURVEYOR

County Surveyor's Comment _____



LEGEND

- = FD HEX BAR w/m in WELL PER AMB 171/43-04
- ▷ = SET LTT LS 4743 1. PMB 171/44-04 HAS CTSB
- ▼ = FD LTT "CITY OF GA" 2 PG 127A. THIS PAGE
CANNOT BE FOUND BY
ME AT THE CITY. !

THE BEARINGS SHOWN HERE
DATUM & ARE SHOWN F

AS "NO REF" THE CITY SCAVENGED
OF 166 TAGS. MORE THAN
LIKELY THE TAGS ARE
SHOWN ON THIS TB. WE
HAVE A REF "NO W".

BURKE.


CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE, California

Brief Legal Description INT. GARDEN GROVE BLVD & KERRY STREET



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/27/05

Signed BRUCE G. HALL L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed _____


Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.



LEGEND


- = FD S&W LS 2681 PER PMB 171/43-44
- = SET LT 4703 IN TC

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

Document Number 2005-0471ACity of Garden GroveCounty of ORANGE

, California

Brief Legal Description E GARDEN GROVE BLVD 675^{FT} EAST OF E
GARDEN

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 3/27/05

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Action 3/27/05Signed BRUCE G. HALLL.S. or R.C.E. No. 0743

COUNTY SURVEYOR'S STATEMENT

APR 11 2005

This Corner Record was received _____

and examined and filed MAY 9 2005Signed RAYMOND L. MATHEL.S. or R.C.E. No. 6185Title COUNTY SURVEYOR


County Surveyor's Comment _____

CORNER RECORD

Document Number 2005-0472 A

City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description S/INT. GARDEN GROVE BLVD & LUCILLE AVE.

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 3/26/05

Signed B. HALL

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 11 2005

and examined and filed MAY 9 2005


Signed R. MATHE

L.S. or R.C.E. No. 6185

Title COUNTY SURVEYOR



County Surveyor's Comment _____



- = FD S&W "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 3 PG 116.
- = FD LTT "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 3 PAGE 116.
- (.) = RECORD PER CITY OF GG TIE BOOK 3 PG 116.


THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM AND ARE SHOWN FOR CONVENIENCE ONLY.

CORNER RECORD

Document Number _____

City of GARDEN GROVECounty of ORANGE

California

Brief Legal Description INT. GARDEN GROVE BLVD & LUCILLE AVE.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/10/01**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/26/01Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____




- = FD S&W "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 3 PG 116.
- = FD LTT "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 3 PAGE 116.
- (.) = RECORD PER CITY OF GG TIE BOOK 3 PG 116.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM AND ARE SHOWN FOR CONVENIENCE ONLY.

CORNER RECORD

Document Number 2005-0473 ACity of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description INT. GARDEN GROVE BLVD & ABBOTT COURT

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 3/26/05

COORDINATES (Optional)

N. _____
 E. _____
 Zone NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Action 3/26/05Signed B. HALLL.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 11 2005and examined and filed MAY 9 2005Signed R. MATHEL.S. or R.C.E. No. 6185Title COUNTY SURVEYOR

County Surveyor's Comment _____



LEGEND

- = FD SET "CITY OF GARDEN GROVE" PER CITY OF GG THE BOOK 2 PG 158.
- ▼ = FD LTT "CITY OF GARDEN GROVE IN TC PER CITY OF GG THE BOOK 2 PG 158.
- ▷ = SET LTT LS 4743 IN TC.
- () = RECORD PER CITY OF GG THE BOOK 2 PG 158.

THE BEARINGS SHOWN HEREON ARE BASED UPON ~~THE~~ AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.


CORNER RECORD

City of GARDEN GROVE

Brief Legal Description INT. GARDEN GROVE BLVD & ABBOTT COURT

Document Number _____

County of Orange, California



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Action 3/26/05

Signed B. Hall

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____


Title _____

County Surveyor's Comment _____

LEGEND

- = FD S&W "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 2 PG 158.
- ▼ = FD LTT "CITY OF GARDEN GROVE IN TC PER CITY OF GG TIE BOOK 2 PG 158.
- ▷ = SET LTT LS 4743 IN T.C.
- () = RECORD PER CITY OF GG TIE BOOK 2 PG 158.

THE BEARINGS SHOWN HEREON ARE BASED UPON ~~THE~~ AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.




- = FD SET "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 3 PG 115.
- ▼ = FD LTT "CITY OF GARDEN GROVE" IN T.C. PER CITY OF GG TIE BOOK 3 PG 115
- ▷ = SET LTT LS 4703 IN T.C.
- () = RECORD PER CITY OF GG TIE BOOK 3 PG 115.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

City of Garden Grove

Document Number _____

County of ORANGE, CaliforniaBrief Legal Description INT. GARDEN GROVE BLVD & HAZEL AVE.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/10/05**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action 3/26/05Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____




- = FD S&W "CITY OF GARDEN GROVE" PER CITY OF GG TIE BOOK 3 PG 115.
- ▼ = FD LTT "CITY OF GARDEN GROVE" IN T.C. PER CITY OF GG TIE BOOK 3 PG 115
- ▷ = SET LTT LS 4743 IN T.C.
- () = RECORD PER CITY OF GG TIE BOOK 3 PG 115.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

Document Number 2005-0475ACity of GARDEN GROVECounty of ORANGE

California

Brief Legal Description E INT GARDEN GROVE BLVD & CANNERY STREE,

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:


SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with


the Land Surveyor's Act on 3/26/05Signed Bruce G. HallL.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 11 2005and examined and filed MAY 9 2005Signed Raymond L. MatheL.S. or R.C.E. No. 6185Title COUNTY SURVEYOR

County Surveyor's Comment _____

NO SCALE

LEGEND

- = FD. STATE MONUMENT IN WELL PER CITY OF GG T.B. 2 PG 122A.
- ▼ = FD LTT "CITY OF GG" IN TC PER CITY OF GG TB 2 PG 122A.
- △ = SET LTT LS 4793 IN TC
- () = RECORD PER CITY OF GG TIE BOOK 2 PG 122A.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.


CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE

California

Brief Legal Description E INT GARDEN GROVE BLVD & CANNERY STREET

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/26/05

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



LEGEND


- = FD. STATE MONUMENT IN WELL PER CITY OF GG T.B. 2 PG 122A.
- ▼ = FD LTT "CITY OF GG" IN TC PER CITY OF GG TB 2 PG 122A.
- △ = SET LTT LS 4793 IN TC
- () = RECORD PER CITY OF GG TIE BOOK 2 PG 122A.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

Document Number 2005-0476ACity of Garden GroveCounty of ORANGE

California

Brief Legal Description E INT GARDEN GROVE BLVD & CASA LINDA
LANE SOUTH

CORNER TYPE

COORDINATES (Optional)

- Government Corner Control
 Meander Property
 Rancho Other

N. _____
 E. _____
 Zone NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Date of Survey 3/10/05Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors Act on 3/26/05Signed B. HALL L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APR 11 2005and examined and filed MAY 9 2005Signed R. MATHE L.S. or R.C.E. No. 6185Title COUNTY SURVEYOR

County Surveyor's Comment _____

- ▲ = FD LTT "CITY OF GARDEN GROVE" IN T.C. PER CITY OF GARDEN GROVE THE BOOK Z PAGE 123A.
- = FD PK & WASHER "CITY OF GARDEN GROVE" PER CITY OF GARDEN GROVE THE BOOK Z PAGE 123A.
- △ = SET LTT LS 0743 IN T.C.
- () = RECORD PER CITY OF GG THE BOOK Z PAGE 123A.



THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.


CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE

, California

Brief Legal Description INT GARDEN GROVE BLVD & CASA LINDA
LANE SOUTH

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors Act on 3/26/05

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____


and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____


Title _____

County Surveyor's Comment _____

- ▲ = FD LTT "CITY OF GARDEN GROVE" IN T.C. PER CITY OF GARDEN GROVE TIE BOOK 2 PAGE 123 A.
- = FD PK & WASHER "CITY OF GARDEN GROVE" PER CITY OF GARDEN GROVE TIE BOOK 2 PAGE 123 A.
- △ = SET LTT CS #743 INT C.



THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM & ARE SHOWN FOR CONVENIENCE.



DISTANCES SHOWN ARE MGR PER CR 2004-1355A


CORNER RECORD

City of GARDEN GROVE

Document Number 2005-0909B

County of ORANGE, Califor

Brief Legal Description EUCLID STREET 958 FT SOUTH OF KATZELA AVE



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 8/10/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on July 4, 2005

Signed B. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 07 2005


and examined and filed OCT 28 2005

Signed J. C. Hornecker L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____



O = SET LT 1 LS 4743 IN TC

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM & ARE SHOWN FOR CONVENIENCE.

CORNER RECORD

City of GARDEN GROVEDocument Number 2005-0710Brief Legal Description POINT WESTMINSTER AVE & ATLANTIS WAY.County of ORANGE, California

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1-3-05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2

A description of the physical condition of the monument as found and as set or reset:
SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Action 5/15/05

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 20 2005

and examined and filed JUN 17 2005

Signed Raymond L. Mathe L.S. or R.C.E. No. 6185

Title COUNTY SURVEYOR



County Surveyor's Comment _____


RESET

10 N-15

PAGE NO. 1
SHEET 1 OF 3

CENTERLINE TIES HASTER STREET

(OTIS AVE SOUTH TO TWNTREE LANE)




SEE SHEET 2

PREPARED IN THE OFFICE OF :

M-K DEVELOPMENT SERVICES
2221 EAST WINSTON ROAD, SUITE K
ANAHEIM, CA 92806
(714) 635-1966 FAX. (714) 635-1204
J.N.02010
MARCH 20, 2003

NO SCALE



CORNER RECORD


City of GARDEN GROVE

Document Number _____

County of ORANGE

, California

Brief Legal Description NE GARDEN GROVE BLVD 675 FT EAST OF E GARDEN



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 3/10/05

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/27/05

Signed BRUCE G. HALL L.S. or R.C.E. No. 0743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____




LEGEND

- GGFB = CITY OF GARDEN GROVE FIELD BOOK.
- = FOUND MONUMENT AS NOTED
- △ = SET LEAD JACK & TAG LS 4743 IN TL
- ▲ = FOUND MONUMENT AS NOTED.

CORNER RECORDDocument Number LC004-1263City of GARDEN GroveCounty of ORANGE

California

Brief Legal Description

MAGNOLIA STREET 7 108' ±NORTH OF CAMPSIDE AVE.**CORNER TYPE**

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 12/1/03**COORDINATES (Optional)**

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on 1/27/04

Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received JUL 22 2004and examined and filed AUG 02 2004Signed Michael K. Sullivan L.S. or R.C.E. No. L.S. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



CENTERLINE TIES ,
WAGNER HALLADAY, INC
SHEET 1 OF 1 SHEET


TRACT NO. 16453, M.M. 849/27-30
ROBERT N. MIM MACK, L.S. 5314

LEGEND:

- INDICATES SET SPIKE AND WASHER STAMPED L.S. 5314, FLUSH.
- INDICATES SET LEAD AND TACK IN PCC CURB
- ∅ INDICATES TANGENT OVER

SCALE: 1" = 20'





~~RECORDED~~


Document Number Z004-1264

City of GARDEN GROVE

County of ORANGE

, California

Brief Legal Description NW CORNER CAMPSON AVE & MAGNOLIA ST.



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 12/01/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/27/04

Signed Brace G. Hall L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUL 22 2004

and examined and filed AUG 02 2004

Signed Michael K. Sullivan L.S. or R.C.E. No. 6254
Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

6 DOROTHY AVE

TB NO 15

PAGE NO 82



LEGEND

- INDICATES 1" IRON PIPE
TAGGED L.S. 5025
- △ INDICATES SET LEAD & TACK
L.S. 5025 ON TOP OF CURB.

TRACT AVE

CITY OF GARDEN GROVE

**STREET
TIES**

SCALE: 1"=40'

DMS

CONSULTANTS.

12377 Louis Street #101
Garden Grove, CA 92840
Phone (714) 740-8841
Fax (714) 740-8842

TRACT No. 16498
TAFT BLVD.

DON E. THOMAS
L.S. No. 5025

**THE
BOOK**


PAGE

DATE: 7/18/04

CORNER RECORD

Document Number 2003-2153City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description E INT. WILSON ST. & LARSON AVE

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 10/23/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See Page 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 22, 2003Signed Bruce G. Hall L.S. or R.C.E. No. 4743


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2003DEC 26 2003

and examined and filed


Signed Michael K. Sullivan L.S. or R.C.E. No. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



- = FO LEAD & TACK TANGENT-OVER TIES IN T.C. PER CITY OF GARDEN GROVE THE BOOK 5 PG 58.
- ▷ = SET SPIKE & WASHER "BRUCE HALL LS 1743" AT 2.00 FOOT OFFSET & TANGENT OVER TO E INTERSECTION.
- () = RECORD PER CITY OF GG THE BOOK 5 PAGE 58.

CORNER RECORD

Document Number 2003-2146 BCity of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description WILSON STREET AT NORTH LINE TRACT NO 11332
MM 507/2245

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 10/23/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 22, 2003Signed Bruce G. Hall L.S. or R.C.E. No. 4743


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2003and examined and filed DEC 26 2003Signed Michael K. Sullivan L.S. or R.C.E. No. 6254
DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

9 de lauron st.

no scale



▼ = FO (END) TIE & TAG LS47A3 PER CR# 2003-2009A.

○ = SET SPIKE & WASHER "BRUCE HALL LS47A3" PER TIES PER
CR# 2003-2009A AFTER SEWER CONSTRUCTION

() = RECORD PER TRACT NO. 11332.


CORNER RECORD

City of GARDEN GROVE

Document Number 2003-2145 B

County of ORANGE, California

Brief Legal Description WILSON 250' + S/LARSON AVE.



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input checked="" type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input type="checkbox"/> |

Date of Survey 10/23/03

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 22, 2003

Signed Brace Hall L.S. or R.C.E. No. 2743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2003

and examined and filed DEC 26 2003

Signed Michael K. Sullivan L.S. or R.C.E. No. L.S. 6254




Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

ELARSON AVE

6


TRACT NO 10700
10/16/1147 DATETRACT NO 10700
10/16/2011

- = SET SPIKE & WASHER "BRUCE HALL LS4743" PER TIES PER CR # 2003-2088A AFTER SEWER CONSTRUCTION
- = FD LEAD JACK & TAG LS4743 IN T.C. PER CR # 2003-2088A UNLESS OTHERWISE NOTED.
- () = RECORD PER TRACT NO 10700

CORNER RECORD

Document Number 2003-2144 BCity of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description WILSON STREET 379'± SOUTH OF LARSON AVE.

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 10/23/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 22, 2003Signed BX Sepp L.S. or R.C.E. No. 4743


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2003and examined and filed DEC 26 2003Signed Michael K. Sullivan L.S. or R.C.E. No. LS. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



- O = SET SPIKE & WASHER "BRUCE HALL LS 4743" PER TIES PER CR # 2003-2087A
- ▼ = FD LEAD, JACK & TAGS LS 4743 IN TC PER CR # 2003-2087A.
- = FD LEAD & JACK IN TC PER CR # 2003-2087A
- () = RECORD PER TRACT 100065.



● = FD RAMSET NAIL IN TC PER CITY OF GARDEN GROVE
TIE BOOK 7 PAGE 72


○ = SET SPIKE & WASHER "BRUCE HALL LS 4743" PER CITY
OF GARDEN GROVE TIE BOOK 7 PAGE 72

DISTANCES SHOWN ARE RECORD & MEASURED PER
CITY OF GARDEN GROVE TIE BOOK 7 PAGE 72

CORNER RECORD

Document Number 2003-2152City of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description C INT. DALE ST. & ACACIA AVE

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 10/23/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with


the Land Surveyor's Action Nov 22, 2003Signed B. G. Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2003and examined and filed DEC 26 2003Signed Michael K. Sullivan L.S. or R.C.E. No. LS. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVEDocument Number 2003-2151 BCounty of ORANGE, CaliforniaBrief Legal Description @ Gloria Ave @ Newano St.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 10/23/03**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2**SURVEYOR'S STATEMENT**


This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Oct. 22, 2003

Signed Bruce G. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT****DEC 05 2003**

This Corner Record was received _____

and examined and filed DEC 26 2003Signed Michael K. Sullivan L.S. or R.C.E. No. LS. 6254Title DEPUTY COUNTY SURVEYOR


County Surveyor's Comment _____



CORNER RECORD

Document Number 2003-2150 BCity of GARDEN GROVECounty of ORANGE

, California

Brief Legal Description DE GLORIA AT EC CURVE 325¹⁴E/D NEWLAND ST.

CORNERS TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 10/23/03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 22, 2003

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2003

and examined and filed DEC 26 2003
Signed Michael K. Sullivan L.S. or R.C.E. No. LS. 6254
Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

PM 23/41

PCL 3

PCL 4

~~NO SONE~~

- = FO LEAD JACK & TAG "GG SURVEY" IN T.C. PER CR # 2003-2093A.
- = SET SPIKE & WASHER "BRUCE HALL LS 4703" AFTER SEWER CONST. PER CR DIES PER CR # 2003-2093A.


CORNER RECORD

Document Number 2003-2149 B

City of GARDEN GROVE

County of ORANGE, California

Brief Legal Description 4 GLORIA AT PEC PM 23/21



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 10/23/03

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 11/22/03

Signed Brace G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2003

and examined and filed DEC 26 2003


Signed Michael K. Sullivan L.S. or R.C.E. No. LS. 6254
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____


✓ NEW LAND

PM 23/41



● = FD LEAD, TACK & TAG "GO SURVEY" PER CR # 2003-2092A

▲ = SET SPIKE & WASHER "BRUCE HALL LS 4743" PER TIES
PER CR# 2003- 2092 A AFTER SEWER CONSTRUCTION



- = FO LEAD JACK & TAG LS4743 IN TC PER CR# 2003-2091A UNLESS OTHERWISE NOTED.
- ▲ = FO LEAD JACK & TAG "CITY OF GARDEN GROVE" IN TC PER CR# 2003-2091A
- △ = SET SPIKE & WASHER "BRUCE HALL LS 4743" PER TIES PER CR# 2003-2091A AFTER SEWER CONST.


CORNER RECORD

Document Number 2003-2148 B

City of GARDEN GROVE

County of ORANGE, California

Brief Legal Description 2 INT NEWLAND ST & CENTRAL AVE.



CORNER TYPE

- | | | | |
|-------------------|--------------------------|----------|-------------------------------------|
| Government Corner | <input type="checkbox"/> | Control | <input type="checkbox"/> |
| Meander | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho | <input type="checkbox"/> | Other | <input checked="" type="checkbox"/> |

Date of Survey 10/23/03

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2


A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on Nov 22, 2003

Signed Brace G. Hall L.S. or R.C.E. No. 1743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC 05 2003


and examined and filed DEC 26 2003

Signed Michael K. Sullivan L.S. or R.C.E. No. ES. 6254

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____



● = FD LEAD, JACK & TIG LS LM3 IN T.C. PER CR# 2003-2090 A

○ = SET SPIKE & WASHER "BRUCE HALL LS 4743" PER TIES PER
CR # 2003-2090 A AFTER SERVER CONSTRUCTION.

CORNER RECORD

City of GARDEN GROVEDocument Number 2003-2147 BCounty of ORANGE, CaliforniaBrief Legal Description DALE STREET AT NORTH LINE PM 281/50**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 10/23/03**COORDINATES (Optional)**


N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:


SEE PAGE 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 11/22/03Signed B. Hall L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received DEC 05 2003and examined and filed DEC 26 2003Signed Michael K. Sullivan L.S. or R.C.E. No. 6254Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE, CaliforniaBrief Legal Description E KNOTT ST AT SE COR TRACT NO 2817.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/1/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
SEE P62

A description of the physical condition of the monument as found and as set or reset:
SEE P62

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/19/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____


examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

C & BELGRAVE AVE

TRACT NO. 2817
MM 118/17-222

▲ = FD LEAD & TACK IN TC PER RI, TO BE DESTROYED.


RI = RECORD PER CITY OF GARDEN GROVE & INTERSECTION TIES
FOR TRACT NO. 2817.

() = RECORD PER RI

△ = SET C, L, S & LS #743 IN T.C.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM.

CORNER RECORD

City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description E KNOTT ST AT 45 COR TRACT NO 2817.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/1/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
SPP A62

A description of the physical condition of the monument as found and as set or reset:
See A62

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/19/07

Signed BRUCE G. HALL P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 26 2007

examined and filed MAR 22 2007

Signed JON C. HORNECKER P.L.S. or R.C.E. No. 7212


Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

C BELGRAVE AVE

MAR 11 8/17-22
1817



▲ = FD LEAD & TACK IN TC PER RI, TO BE DESTROYED

RI = RECORD PER CITY OF GARDEN GROVE & INTERSECTION TIES
FOR TRACT NO. 2817.

() = RECORD PER RI


△ = SET C, L, & T LS 4743 IN TC.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM.

CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE, CaliforniaBrief Legal Description E INT OF KN077 ST & BEZGRAVE AVE.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation: _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Date of Survey 2/1/07Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on 2/1/07Signed Bruce G. HallP.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE & TIES FOR MARCH
NO 2817,


() = RECORD PER RI

\blacktriangle = FO L&T AS NOTED

Δ = L&T L,T,ET LS 4743 IN TC

THE BEARINGS SHOWN HEREON ARE BASED UPON ~~ST~~ ASSUMED
DATA.

CORNER RECORD

Document Number 2007-0346 ACity of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description E INT OF KNOTT ST & BEGRAVE AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/1/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
SEE PG 2

A description of the physical condition of the monument as found and as set or reset:
SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/12/07

Signed B. Hall P.L.S. or R.C.E. No. 4793




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 26 2007
examined and filed MAR 22 2007

Signed J.C. Haas P.L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE & TIES FOR TIME 7
NO 2817,

() = RECORD PER RI

▲ = FO L&T AS NOTED


△ = L&T L,T, ET LS 4743 IN TC

THE BEARINGS SHOWN HEREON ARE BASED UPON ~~ST~~ ASSUMED
DIAZM. AN

CORNER RECORD

City of Garden Grove

Document Number _____

Brief Legal Description INT KNOTT ST. & BELGRAVE AVECounty of ORANGE, California**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/1/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/19/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____


County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 3 PAGE 29
() = RECORD PER RI
● = FD L77 "GARDEN GROVE SURVEY" IN TC PER RI UNLESS NOTED OTHERWISE
▲ = FD L77 LS 5411 IN TC per CR 2007-0099
() = Record per CR 2007-0099

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

Document Number 2007-0345 ACity of Garden GroveCounty of ORANGE, CaliforniaBrief Legal Description 2117 KNOTT ST. & BELGRAVE AVE

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/10/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2


A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/19/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 26 2007


examined and filed MAR 22 2007

Signed Jon C. Hornecker P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 3 PAGE 29


() = RECORD PER RI

● = FD LTT "GARDEN GROVE SURVEY" IN TC PER RI UNLESS
NOTED OTHERWISE

▲ = FD LTT LS 541 IN TC NO REF.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN
ASSUMED DATUM.

CORNER RECORD

City of Garden GroveCounty of ORANGE, California
Brief Legal Description E OF KNOTT ST 723± SOUTH OF E CHAPMAN AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/1/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

See Pg 2

A description of the physical condition of the monument as found and as set or reset:

See Pg 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/19/07

Signed B. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



R1 = RECORD PER CITY OF GREENSBORO TIES FOR TRACT NO
4015 MM 140/06-07.


() = RECORD PER R1

● = FD REMAINS OF SPIKE SHAFT ON D.3!

▲ = FD L&T IN TC PER R1

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM.

CORNER RECORD

City of Garden GroveCounty of Ocana, California
Brief Legal Description E OF KELLY ST 723'± SOUTH OF E
CHARLES AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/1/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.
See Pg 2A description of the physical condition of the monument as found and as set or reset:
See Pg 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/19/07Signed B.G. Hall P.L.S. or R.C.E. No. 4743


COUNTY SURVEYOR'S STATEMENT

FEB 26 2007

This Corner Record was received _____

examined and filed MAR 22 2007Signed J.C. Hall P.L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE TIES FOR TRACT NO
4015 MM 140/06-47.


() = RECORD PER RI

● = FD REMAINS OF SPIKE SHAFT ON D.3!

▲ = FD LET IN TC PER RI

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM.

CORNER RECORD

City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description 4 KNOT 57 175' SOUTH OF CHAPMAN AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/1/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/19/07

Signed Bruce G. Hall

P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____


examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

Cochran Ave.

FD 1³/8" BASS CAP w/pms
IN WELL PER R2


R1 = RECORD PER CITY OF GARDEN GROVE TIES FOR TRACT NO 4015.

22 = RECORD PER RS8 TB150

- () = RECORD PER R1 UNLESS OTHERWISE NOTED.
- = FD MONUMENT AS NOTED.
- ▲ = FD LEAD & TACK IN TC PER R1 TO BE DESTROYED.
- = SET LT&T IN TC STAMPED LS 4743.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description E KNOTT ST 175' SOTH OF CHAPMAN AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/19/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PL 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PL 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/19/07

Signed B. G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 26 2007


examined and filed MAR 22 2007

Signed J.C. Hornecker P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____



THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

AS SHOWN




- ▲ = E INT. FD PK & CITY OF GARDEN GROVE SURVEY DEPT.
WASHER, ~~RECORDED~~ PER CITY OF GG THE BOOK NO. 8 PG 81.
- = FD LT7 CITY OF GARDEN GROVE SURVEY RP IN TC, ~~RECORDED~~
PER CITY OF GG THE BOOK NO. 8 PG 81.
- = SET LT7 LS 4743 IN TC.

THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED
DATUM

[] = RECORD PER CITY OF GG THE BOOK NO. 8 PG 81.

CORNER RECORD

City of Garden GroveCounty of Orange, Calif.Brief Legal Description INT. MAGNOLIA STREET & MARLENE AV.Document Number 2007-0005 A

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 12/27/06

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83 _____
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88 _____
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner

SEE PG 2

A description of the physical condition of the monument as found and as set or reset

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Action 12/30/06

Signed Bruce G. Hall

L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received JAN 12 2007

and examined and filed MAY 14 2007


Signed J.C. Hall

L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



- = FD LT7 "GARDEN GROVE SURVEY RP" IN T.C. ~~AS SHOWN~~ PER CITY OF GG THE BOOK NO. 8 PG 83.
- ▲ = FD PK & WASHER "CITY OF GARDEN GROVE SURVEY DEPT" ~~AS SHOWN~~ PER CITY OF GG THE BOOK NO. 8 PG 83.
- = FD RANGE SET & TAG "STATE OF CALIFORNIA DIV OF HWYS" IN T.C PER AOR039C PG 0203.
- () = RECORD PER AOR039C PG 0203.
- [] = RECORD PER CITY OF GG THE BOOK NO. 8 PG 83.
THE BEARINGS SHOWN HEREON ARE BASED UPON AN ASSUMED DATUM.


CORNER RECORD

City of Green BraeDocument Number 2007-0004 A

Brief Legal Description

County of OCEANIC

Califor

Brief Legal Description 217 MAGNOLIA STREET & BLOSSOM AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 12/27/06

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD8
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 12/27/06

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 12 2007
and examined and filed MAY 14 2007

Signed John C. Horneck L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE, California
Brief Legal Description INT GARDEN GROVE BLVD & TAFT ST.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07**COORDINATES (Optional)**


N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/21/07Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____

examined and filed _____


Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

~~STAFF ST~~

FD PER GGTB 2 PG 136B



R1 = RECORD PER CITY OF GARDEN GROVE TIE BOOK 3 PG 108A.

() = RECORD PER R1

GGTB = CITY OF GARDEN GROVE TIE BOOK


- = FD PL & WASHER "CITY OF GARDEN GROVE" PER R1 UNLESS OTHERWISE NOTED.
- ▼ = FD LTT "GARDEN GROVE SURVEY" PER R1 UNLESS OTHERWISE NOTED.
IN T.C.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATA

CORNER RECORD

Document Number 2007-0403 ACity of Garden GroveCounty of Orange

California

Brief Legal Description INT GARDEN GROVE BLVD & TAFT ST.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/21/07

Signed B.G.Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007


examined and filed APR 13 2007

Signed J.C. Hornecker P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE THE BOOK 3 PG 108A.

() = RECORD PER RI

GG7B = CITY OF GARDEN GROVE THE BOOK


● = FO PK & WASHER "CITY OF GARDEN GROVE" PER RI UNLESS OTHERWISE

NOTED.

▼ = FO LTT "GARDEN GROVE SURVEY" PER RI UNLESS OTHERWISE NOTED.
IN T.C.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM

CORNER RECORD

City of Garden GroveCounty of Ocana, CaliforniaBrief Legal Description POINT OF GARDEN GROVE BLVD (OLD) & TAFT ST &
GROVE AVE.**CORNER TYPE**

Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEC PG 2

A description of the physical condition of the monument as found and as set or reset:
SEC PG 2

SURVEYOR'S STATEMENTThis Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/21/07Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE THE BOOK Z PG 136B.


() = RECORD PER RI

▼ = FO LTT "GARDEN GROVE SURVEY" IN TC PER RI

● = FO PK & CITY OF GARDEN GROVE MAPS FOR PER RI.

THE BEARINGS SHOWN HEREON ARE BASED UPON
AN ASSUMED DATUM.

CORNER RECORD

Document Number 2007-0402 ACity of Garden GroveCounty of Ocana, CaliforniaBrief Legal Description 4 INT OF GARDEN GROVE BLVD (OLD) & TAFT ST.
GROVE AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/21/07


Signed B.G. Hall P.L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007
examined and filed APR 13 2007

Signed J.C. Hornecker P.L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE THE BOOK Z PG 136B.

() = RECORD PER RI


▼ = FD LTT "GARDEN GROVE SURVEY" IN TC PER RI

● = FD PK & CITY OF GARDEN GROVE WARDER PER RI.

CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE, CaliforniaBrief Legal Description 2 CONSY GARDEN GROVE BLVD AT PRC 134 1/4
EAST OF E ZAFT ST.**CORNER TYPE**

Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2

A description of the physical condition of the monument as found and as set or reset: _____

SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/20/07Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



R1 = RECORD PER CITY OF GARDEN GROVE TIE BOOK 3 PG 109A.

() = RECORD PER R1

● = FD PK & CITY OF GARDEN GROVE WASHCR PER R1 AT PRC.


▲ = FD LTY "GARDEN GROVE SURVEY" IN TC PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

Document Number 2007-0401 ACity of GARDEN GROVECounty of ORANGE

California

Brief Legal Description 4 CONSY GARDEN GROVE BLVD AT PRC 139' EASY OF 4 ZAFZ ST.

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation. _____
 Vertical Datum: NGVD29 NAVD88
 Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/20/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007


examined and filed APR 13 2007

Signed J.C. Hornecker P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



R1 = RECORD PER CITY OF GARDEN GROVE TIE BOOK 3 PG 109A.

() = RECORD PER R1


● = FD PK & CITY OF GARDEN GROVE WASHER PER R1 AT PRC.

▲ = FD LTT "GARDEN GROVE SURVEY" IN TC PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of GARDEN GROVE County of ORANGE, California
Brief Legal Description NE 1/4 OLD & GROVE AVE WITH NE ALLEY



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PL 2

A description of the physical condition of the monument as found and as set or reset:

SEE PL 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/21/07

Signed B. Hall P.L.S. or R.C.E. No. 9793



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____



R1 = RECORDED PER CITY OF GARDEN GROVE THE BOOK 3 PG 109A.

() = RECORDED PER R1

▲ = FD LTT "GARDEN GROVE SURVEY" IN TC PER R1

● = FD INT OF 4-SAW STRADDLERS AROUND SMH PER R1
AT E INT OLD GROVE AVE. & ALLEY.


THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM

CORNER RECORD

City of GARDEN GROVEDocument Number 2007-0400 ACounty of ORANGE

, California

Brief Legal Description

NE 1/4 OLD & GRAVE AVE WITH E ALLEY

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/20/07

Signed B. Hall P.L.S. or R.C.E. No. 2743



COUNTY SURVEYOR'S STATEMENT


MAR 05 2007

This Corner Record was received _____


examined and filed APR 13 2007

Signed J.C. Hall P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK 3 PG 109A.

() = RECORD PER R1

▲ = FD LT "GARDEN GROVE SURVEY" IN TC PER R1


● = FO INT OF 4-SQW STRADDLERS AROUND SMH PER R1
AT & INT OLD GROVE AVE. & ALLEY.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM

CORNER RECORD

Document Number 2007-0399 ACity of Garden GroveCounty of Orange

California

Brief Legal Description 2117 GARDEN GROVE BLVD & ALLEY 178' E/O d
GROVE AVE.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/21/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007


examined and filed APR 13 2007

Signed Jon C. Hornecker P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____



RI = RECORD PER CITY OF GARDEN GROVE THE BOOK 3 PG 109A.

() = RECORD PER RI

▲ = FD LTT "CITY OF GARDEN GROVE" IN TC PER RI UNLESS OTHERWISE NOTED.

● = FD INT OF 4- PUNCH MARKS IN MH RIM PER RI, A7 & INT.


THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM,

CORNER RECORD

Document Number _____

City of Garden GroveCounty of Orange

California

Brief Legal Description 2117 GARDEN GROVE BLVD & ALLEY 178' E/O &
GROVE AVE.

CORNER TYPE

COORDINATES (Optional)

- Government Corner Control
Meander Property
Rancho Other

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Date of Survey 2/20/07Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:


SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/21/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____




R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK 3 PG 109A.

() = RECORD PER R1

▲ = FD L77 "CITY OF GARDEN GROVE" IN TC PER R1 UNLESS OTHERWISE NOTED.

● = FD INT OF 4- PUNCH MARKS IN MH RIM PER R1, A7 & INT.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM,




R1 = RECORD PER CITY OF GARDEN GROVE TIE BOOK 3 PG 96 A.

() = RECORD PER R1

▲ = FD LT "GARDEN GROVE SURVEY" IN TC UNLESS OTHERWISE NOTED.

● = FD PK & CITY OF GARDEN GROVE WASTER PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.



RI = RECORD PER CITY OF GARDEN GROVE TIE BOOK 3 PG 96 A.

() = RECORD PER RI


▲ = FD L77 "GARDEN GROVE SURVEY" IN TC UNLESS OTHERWISE NOTED.

● = FD PL & CITY OF GARDEN GROVE WASTER PER RI.

() = Record Per CR 2007-0102

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

Document Number 2007-0398 ACity of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description POINT OF GARDEN GROVE BLVD & PINE STREET
XACATED

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/22/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007
examined and filed APR 13 2007

Signed J.C. Johnson P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVE

Document Number _____

County of ORANGE, California
Brief Legal Description POINT OF GARDEN GROVE BLVD & PINE STREET
XACATED**CORNER TYPE**

Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07**COORDINATES (Optional)**


N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/22/07Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____


examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

CORNER RECORD

Document Number 2007-0397 ACity of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description S E C GARDEN GROVE BLVD AT LINCOLN ST.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2


A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/22/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007


examined and filed APR 13 2007

Signed J.C. Hornecker P.L.S. or R.C.E. No. 7212



Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK 3 PG 96A.


C1 = RECORD PER R1

▲ = FD LT "GARDEN GROVE SURVEY" IN TC UNLESS OTHERWISE NOTED.

● = FD PK & CITY OF GARDEN GROVE WASHER PER R1

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of GARDEN GROVECounty of ORANGE, CaliforniaBrief Legal Description SW 1/4 EC GARDEN GROVE BLVD AT LINCOLN ST.**CORNER TYPE**

Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner.

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/22/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____


County Surveyor's Comment _____

FD LTT LS 5562
IN TC NO REF.

FD LTT LS 5541

IN TC Per

CR 2007-0102



R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK 3 PG 96A.

(C) = RECORD PER R1

▲ = FD LTT "GARDEN GROVE SURVEY" IN TC UNLESS OTHERWISE NOTED.

● = FD PK & CITY OF GARDEN GROVE MASTER PER R1


THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM

CORNER RECORD

Document Number _____

City of GARDEN GROVECounty of ORANGE

California

Brief Legal Description 2107 OF GARDEN GROVE BLVD & LINCOLN ST.**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Date of Survey 2/22/07Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/22/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

FD LTT LS 5562
IN TC NO REF.FD LTT LS
5411 IN TC Per
CR 2007-0102

R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK 3 PG 96A.

() = RECORD PER R1

▲ = FD LTT "GARDEN GROVE SURVEY" IN TC PER R1 UNLESS OTHERWISE NOTED

● = POINT INT OF 4 PUNCH MARKS IN MH RIM PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED MDTM.


City of GARDEN GROVE

County of ORANGE

, California

Brief Legal Description

POINT OF GARDEN GROVE BLVD & LINCOLN ST.



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/22/07

Signed BRUCE G. HALL P.L.S. or R.C.E. No. 4743




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007


examined and filed APR 13 2007

Signed J.C.B. P.L.S. or R.C.E. No. 7212

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment



R1 = RECORD PER CITY OF GARDEN GROVE TIE BOOK 3 PG 96A.


() = RECORD PER R1

▲ = FD LTT "GARDEN GROVE SURVEY" IN TC PER R1 UNLESS OTHERWISE NOTED

● = FD INT OF 4 PUNCHED MARKS IN MH RIM PER R1.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.


NO SCALE



- R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK 2 PG 137A.
() = RECORD PER R1
▲ = FO LTT "GARDEN GROVE SURVEY" IN BRICK SIDEWALK PER R1
● = FO HEX BAR W/PIR IN WELL PER R1 ON 1.3'
○ = SET CTT LS 4743 IN TC.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.


1/6 SCALE



- R1 = RECORD PER CITY OF GARDEN GROVE THE BOOK 2 PG 137A.
- () = RECORD PER R1
- ▲ = FO LTT "GARDEN GROVE SURVEY" IN BRICK SIDEWALK PER R1
- = FO HEX BAR W/PM IN WELL PER R1 DN 1.3'
- = SET CTT LS 4793 IN TC.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

City of GARDEN GROVE County of ORANGE, California
Brief Legal Description INT GARDEN GROVE BLVD & MAIN ST. GPS 3033



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/20/07

Signed B. G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007
examined and filed APR 13 2007

Signed J. C. Hornecker P.L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR




County Surveyor's Comment _____

CORNER RECORD

City of GARDEN GROVEBrief Legal Description INT GARDEN GROVE BLVD & MAIN ST.

Document Number _____

County of ORANGE, California**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/21/07

Signed B.G. Hall P.L.S. or R.C.E. No. 4743

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____


examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____

City of GARDEN GROVE County of ORANGE, California
Brief Legal Description EAST GARDEN GROVE BLVD & WALNUT ST (VACATE)



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2


A description of the physical condition of the monument as found and as set or reset:

SEE PG 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/22/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 05 2007


examined and filed APR 13 2007

Signed J.C. Hornecker P.L.S. or R.C.E. No. 7212


Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment



CORNER RECORD

City of Garden GroveCounty of OcanaCo, CalifBrief Legal Description WALMART STREET AT Garden Grove Blvd.Document Number 2007-0627

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 3/13/07

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial
 U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

CSE P62

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 3/13/07

Signed J.C. HallL.S. or R.C.E. No. 4743


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 15 2007

and examined and filed MAY 17 2007

Signed J.C. HallL.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____




• = FD LTT RCE 13542 IN ADA RAMP TO BE DESTROYED BY NEW ADA RAMP CONSTRUCTION NO REF.

⊖ = SET LTT LS 4743 IN TC

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of Garden Grove Document Number _____
County of Orange, California
Brief Legal Description WALNUT STREET AT GARDEN GROVE BLVD.



CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 3/13/07

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2.


A description of the physical condition of the monument as found and as set or reset:

SEE PG 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 3/13/07

Signed Bruce G. Hall L.S. or R.C.E. No. 4743



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____

and examined and filed _____

Signed _____ L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____




- = FD L77 RCE 13542 IN ADA RAMP TO BE DESTROYED BY NEW ADA RAMP CONSTRUCTION NO REF.

θ = SET L77 LS 4743 IN TC

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM.

CORNER RECORD

City of Garden GroveCounty of Orange, CaliforniaBrief Legal Description 2117 GARDEN GROVE BLVD & WALNUT ST (vacated)**CORNER TYPE**

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 2/20/07**COORDINATES (Optional)**

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elevation. _____
Vertical Datum: NGVD29 NAVD88
Units: Metric Imperial U.S. Survey

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PG 2

A description of the physical condition of the monument as found and as set or reset:

SEE PG 2**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 2/22/07

Signed Bruce G. Hall P.L.S. or R.C.E. No. 2743**COUNTY SURVEYOR'S STATEMENT**


This Corner Record was received _____

examined and filed _____

Signed _____ P.L.S. or R.C.E. No. _____

Title _____

County Surveyor's Comment _____




THE BEARINGS SHOWN ARE BASED UPON AN ASSUMED DATUM

FD PK & WASHER LS 5411
FLUSH PER COASTER RECORD
2003-941B

DELAIRD ST.

~~NO SCALE~~

TRACT NO 2519
MM 79/20-21




() = RECORD PER TRACT NO. 2519 MM 79/20-21

▲ = FD MONUMENT AS NOTED.

○ = SET LTY LS 4743 IN T.C.

THE BEARINGS SHOWN HEREON ARE BASED UPON
AN ASSUMED DATUM

CORNER RECORD

City of GARDEN GROVEDocument Number 2007-0194 ACounty of ORANGE, CaliforniaBrief Legal Description E GARDEN GROVE BLVD 110' WEST OF
E CAIN STREET.

CORNER TYPE

- Government Corner Control
Meander Property
Rancho Other

Date of Survey 1/17/07

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial
U.S. Survey foot

Corner — Left as found Found and tagged Established Reestablished Rebuilt Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PG 2A description of the physical condition of the monument as found and as set or reset:
SEE PG 2


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on 1/17/07Signed B.G.Hall L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 30 2007
and examined and filed MAR 05 2007Signed J.C. Hornecker L.S. or R.C.E. No. 7212
Title DEPUTY COUNTY SURVEYOR


County Surveyor's Comment _____



- = FD HEX BAR W/PM IN WELL PER PMB 192) 1-4 DN 1.8.
- = FD LTT "GARDEN GROVE SOCIETY" IN TC NO REF.
- ▼ = FD CHIS + IN TC NO REF. SET LTT LS 4743 IN TC
- = SET LTT LS 4743 IN T.C.

THE BEARINGS SHOWN ARE BASED UPON AN ASSUMPTION

CORNER RECORD

City of GARDEN GROVEBrief Legal Description 41st GARDEN GROVE BLVD & BURGESS STREETDocument Number 2007-0415County of ORANGE, California

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation. _____
 Vertical Datum: NGVD29 NAVD88
 Units: Metric Imperial U.S. Survey

Date of Survey 1-26-07Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found; Evidence used to identify or procedure used to establish or reestablish the corner:


SCE PG 2

A description of the physical condition of the monument as found and as set or reset:

SCE PG 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on 2/25/07


Signed Bruce G. Hall P.L.S. or R.C.E. No. 4743

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAR 01 2007examined and filed MAY 17 2007Signed J.C. Hornscher P.L.S. or R.C.E. No. 7212Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____

R-1 = COUNTY OF ORANGE
C.R. 2003 - 234A.



NOTHING RD. SET PRIM L.S. 5.5411 PER TIES
SHOWN ON R-1.

FD. GARDEN GROVE LIT IN TOP OF CURB PER R-1.

FD. LIT L.S. 5.5411 IN TOP OF CURB PER R-1.


The purpose of this record is to document the perpetuation of found monument(s).
No claim is made regarding the correctness of the position(s) of said
monument(s), nor the dimensional relationship to street centerlines or property
boundaries.

02-RJN-095

CORNER RECORD

Document Number 2003-936 BCity of Garden GroveCounty Orange, CaliforniaBrief Legal Description Garden Grove Blvd & Partridge Street.

SEP 27 2006

**CORNER TYPE**

Government Corner Control
Meander Property
Rancho Other
Date of Survey 03/10/03

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found as described on the reverse of this sheet.

A description of the physical condition of the monument as found and as set or reset:
These ties are for the purpose of perpetuating the found monumentation. No claim is made as to the relationship of the points or lines shown hereon to true boundary location.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on April 1, 2003

Signed  P.L.S or R.C.E. No. L.S. 5411

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received APR 21 2003

MAY 20 2003

and examined and filed

Signed  P.L.S or R.C.E. No. L.S. 6254

Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment